

Structure No:	
Team Leader:	
WI Inspector No:	
Date:	

Inspection team leader to complete this form upon review for conditions that might affect the applicability of the method to establish redundancy per SIM Section 1.3.5.7. Include this completed form with the inspection report in HSIS. See specific inspection procedures in the inspection report for location of members critical to the alternate load path.

Yes	No	Structural review required if any of the following applies to SRM	Comments
		Fatigue crack that has not been effectively arrested.	
		A primary load carrying member in CS4.	
		Unresolved impact damage to primary load carrying members, such as stress risers (cracks, sharp reentrant corners) or large out-of-plane distortion.	
		CS3 or CS4 distortion in the bottom flange or web of the tub girders in the negative moment region.	
		CS3 or CS4 distortion in the bottom flange or web of the exterior diaphragms.	
		Missing bolts in field splices or external diaphragm to girder connections.	
		Cracks, distortion, or CS4 section loss in the external diaphragms and/or missing bolts in diaphragm-to-girder connections.	
		Exposure to intense, prolonged, or high temperature fire.	
		The position or number of striped lanes has changed.	
		Change in deck overburden or other increase in dead load to the superstructure.	
		Removal of external diaphragms (not allowed).	
ddit	ional	Notes:	
		g Yes above , notify the inspection program manager and i b for the SRM and select Structural Review activity type as	
ıspe	ection	program manager	Date Notified