Communication	Navigation	Services
CTAF ..... 122.9 APP/DEP 135.25	**Elevation ..... 976'** **TPA ..... 1976'**	**FUEL: 100LL** **24 HR Self-Serve** **Airport Manager** **608-339-3919**
	VOR to Field: 117.0 DLL 355°/25 NM	

NOTES: 1. Ultralight activity at airport.
2. Runway 08/26 closed Dec. 1–April 1.
3. Aircraft departing runway 15 requested turn to a heading of 180° after takeoff.