Communication	Navigation	Services
CTAF ..... 122.7 APP/DEP ..... 135.45 FSS 122.1R 117.0T	**Elevation ..... 824'** **TPA ..... 1824'** **VOR to Field:** 117.0 DLL 084°/12 NM	**FUEL: MOGAS, 100LL** **24 HR Self-Serve** **Air Portage** **608-742-3300**

NOTES: 1. Large buildings and trees beside runway 35 causes wind shear with strong northwest winds.
2. 110' power lines located 1580' south of runway 35
3. Runway 04-22 closed Nov. 15 to Apr. 15.