



Contaminated Site Assessment/Remediation Process



Hazardous Materials Assessment Schedule



- A. Phase 1 investigations scheduled prior to CDR or OPM.
 - B. Phase 1 investigations completed, recommendations for further investigation reviewed.
 - C. Phase 2 investigations completed. Determine if WisDOT should proceed with Phase 2 1/2 or 3 investigations or proceed with PECFA agency. Discuss project schedule with RPs.
 - D. Perform Phase 2 1/2 - 3 investigations.
 - E. Phase 3 complete (including DNR/Commerce concurrence) when Department is RP.
 - F. Special provisions for remediation during construction complete, or remediation prior to construction underway.
- Lead times shown are the minimum needed to ensure that plans are ready for the PS&E submittal date.**

* This can be done prior to the Operational Planning Meeting.