

# 2014 Independent Assurance Program Annual Meeting

Tuesday, December 9, 2014 (9:00 AM - 5:00 PM)  
Wednesday, December 10, 2014 (8:00 AM - Noon)

Hosted by: Northeast Region - Chula Vista Resort  
Wisconsin Dells, WI

## AGENDA

Topic	By
<b>December 9 (9:00 A.M.)</b>	
⇒ Welcome, Introductions, Housekeeping	Becky Rooyakkers – NER TSS Sup (20 min.)
⇒ Agenda Order and Additional Topics	All
⇒ <a href="#">HTCP Update</a>	Ray Spellman – HTCP Director (10 min.)
⇒ Introduce New QMP Engineer/Staff Changes	Jim Parry (10 min.)
⇒ <a href="#">Region IAP Annual Reports</a>	All Regional IA Specialists (2 hrs) (Reports 15 min. max each)
⇒ IAP Reporting and Evaluations	
⇒ IAP Observation/test Result Interpretation	
⇒ Analysis and Review Split Sample Results	
⇒ Correlation tolerances	
⇒ Follow up Testing and Investigations	
⇒ MTS Reporting & Distribution of Reports	
⇒ Lab Qualification	Ken Nwankwo (10 min.)
⇒ Region Labs- AMRL proficiency sample results	
⇒ 2014 Consultant Laboratory Inspection Update	
<b>Noon – 1:00 P.M. LUNCH (On your own)</b>	
⇒ <a href="#">FHWA Update</a>	Dave Kopacz – FHWA (40min.)
⇒ <a href="#">Non-Conformance/Performance Issue</a>	Don Greuel (30 min.)
⇒ <a href="#">Finals/Materials Process Update</a>	Don Greuel (30 min.)
⇒ <a href="#">Sampling and Testing Statistical Analysis</a>	Joe White (45 min.)
⇒ 10 MIN BREAK	
⇒ 90% IA Reporting, MTS and MRS Enhancements	Gary Lynch, Ryan Seffrood (30 min.)
⇒ Materials User Group Re-Initiation	All (10 min.)
⇒ E-Guide Committee/Revisions	All (15 min.)
<b>Adjourn – 5:00 P.M.</b>	

# 2014 Independent Assurance Program Annual Meeting

Tuesday, December 9, 2014 (9:00 AM - 5:00 PM)  
Wednesday, December 10, 2014 (8:00 AM - Noon)

Hosted by: Northeast Region - Chula Vista Resort  
Wisconsin Dells, WI

## AGENDA

Topic	By
<b>December 10 (8:00 A.M.)</b>	
⇒ <a href="#">Nuclear Density Update</a>	Mike Bohn (5 min.)
⇒ <a href="#">Non-Performance QMP C&amp;M 8-30</a>	Bob Schiro – All (20 min.)
⇒ <a href="#">IA Program Overview</a>	Joe White, Jim Parry (45 min.)
⇒ Review “December 2012 Independent Assurance Program Guide”	
⇒ Best Practices, Tracking Who Needs to be IA’d	
⇒ IA Equipment Needs/Requirements	
⇒ Nuke Density Testing Locations/Correlations	
⇒ <a href="#">Binder, Emulsion Updates and Sample Card Prep</a>	Dick Barden (15 min.)
⇒ Aggregate Source Locations, Blended Samples	Matt Andreini (10 min.)
⇒ 10 MIN BREAK	
⇒ <a href="#">HMA Mix Area</a>	Judie Ryan (30 min.)
⇒ HMA QMP Standard Notification Process Mix Failure	
⇒ Outline of 2014 FAQ Categories	
⇒ Mix Design life, Vision for 2015	
⇒ <a href="#">HMA and Other Specification Updates</a>	Barry Paye (30 min.)
⇒ <a href="#">IRI QV Update 2014</a>	Joe Wilson (10 min.)
⇒ <a href="#">QV Pre-cast Program, 2014 MITSCAN, PCC Update</a>	Peter Kemp (20 min.)
⇒ <a href="#">Base Course Small Quantities</a>	John Brophy (10 min.)
⇒ Beam Guard Update	Jeff Michalski (10 min.)
⇒ Next IA Meeting/Location	All
Adjourn – Noon	