

Base course small quantities

1. Under 6000 tons, QV testing is optional. I have seen some project engineers still taking the first day of placement testing.
2. QC production test passes and QV test fails – what to do?
3. Example; 8000 tons from two different sources.
 - a) Optional since it was less than 6000 tons for one source.
 - b) Two QV tests for both sources for a total of four QV tests.
4. Notification of source changes should be pre-placement.