

Part-Chapter	Page number	General Description of Change
1-2	3	minor edit
1-2	7	minor edit
1-2	11-12	updated language for Assistant Statewide Program Manager
1-2	16	included reference for Ancillary TL qualifications
1-2	17	updated time period for when other bridge experience exists and emphasized experience over the last X year period
1-2	17	add mandatory annual WisDOT Structure Inspection Refresher Training
1-2	19	added language supplemental qualification guidance
1-2	30	minor edit
1-2	38	updated form number
1-2	42	changed Jan 15th to Feb 1st., minor edit
1-2	45	minor edit
1-3	chapter wide	changed floor beam to floorbeam
1-3	9	updated reference to section
1-3	21	deleted FHWA reference language
1-3	21-22	new language to emphasize scour and importance of UW profiles and determining scour and moved other scour language here
1-3	23	closed cell structures don't require UW profile, probing at apron ends, documenting on UW probe form
1-3	23	minor edit
1-3	23-24	Underwater profile in conjunction with dive and hydrographic survey language updated
1-3	27	added other high risk criteria
1-3	25-26	Added section 1.3.7 Scour Monitoring Inspection
1-3	27	uw dive required when probing or observations cannot be completed during low flows for water 4' or less
1-3	27	minor edit
1-3	31,32	updates to dive interval criteria for extended and reduced.
1-3	38	rename section as Underwater Probing and minor edits
1-3	39	added guidance on when underwater probing should be completed when not done with the routine inspection
1-3	42	added where the service inspection is located in HSI.
1-3	42	Updated figure number
1-3	43	added annual movable systems inspection is recommended
1-3	45,46	Added Closed Bridge Criteria section and language
1-3	49,50	added when POA's are required.
1-3	50,51	added guidance for vertical clearance document entry into HSI
1-3	53	minor edits
1-4	chapter wide	update section numbers and TOC

1-5	chapter wide	updated section numbering and TOC
2-A	16	update defect 1140 name
2-A	17	update defect 1150 defect condition state language to match field manual
2-1	14	minor edit
2-3	chapter wide	updated section numbering
2-3	3	added guidance on overburden depth to be included in HSI and inspection report., minor edit
2-3	10	added overburden depth guidance reference
2-3	11	minor edit
2-3	42	added median and sidewalk count toward NBI deck condition rating.
2-4	82,94,11 9,122,13 2,135	assessment 9170 name corrected
2-4	82	minor edit
2-4	96	minor edit
2-4	98	minor edit
2-5	57	changed assessment 8250 to 9250 and name
2-5	36	updated assessment 9250 name
2-6	chapter wide	changed lineal to linear
2-6	17-19	added Median and sidewalk elements section
2-6	21	minor edit
2-7	6	removed median and sidewalk assessments
2-7	26	minor edit
2-8	5	deleted bullet to make sure artificial slope stabilization is in place and minor edit
2-8	6	deleted bullet checking condition of channel protection devices rip and how riprap and channel lining info
2-8	6	deleted bullet to make sure artificial slope stabilization is in place
2-8	8	deleted the words channel protection
2-8	9	deleted the words channel protection
2-8	11	minor edit
2-8	12-13	added procedure for evaluation of scour at in-service structures language
4-1	2	updated formating of TL sign/Signal/HML qualifications and other minor edits

4-4	31	minor edit
-----	----	------------