

		STSPLOG (Standardized Special Provisions) June 15, 2011 Updates
DATE	PROVISION #	COMMENTS
6/15/2011	100-005	General: Revised.
6/15/2011	107-026	Railroad Insurance and Coordination updated STSP UPR contact information.
6/15/2011	107-034	Railroad Insurance and Coordination STSP E1: deleted Union Pacific and updated BNSF flagging rates; STSP E2: updated Canadian Pacific (Soo Line) flagging rates; STSP E4: updated Wisconsin & Southern Railroad Company flagging rates; STSP E5: updated CN Railroad flagging rates; <i>added STSP E6</i> : added E6 for Union Pacific flagging rates.
6/15/2011	107-055	Environmental Protection, Aquatic Exotic Species Control Revised statute number.
6/15/2011	107-200	Native American Employment. Changed language for Tribal Contact Information. Changed contact information for WisDOT Tribal Liaison. <i>Added STSP NAEI.</i>
6/15/2011	205-009	Grading, Shaping and Finishing for Barrier Terminals, Item 205.9006.S: <i>Deleted.</i> This work is now in standard spec 614 under bid item 614.0010, Barrier System Grading Shaping Finishing.
6/15/2011	206-005	Temporary Shoring, Item 206.6000.S. <i>New bid item.</i> Updated to change measurement to SY and clarify measurement for staged construction in multiple configurations without removal and reinstallation.
6/15/2011	415-010	Concrete Pavement Fast Track, ___-Inch, Item 415.1150.S. Updated reference from 415.3.17 to 415.3.15.
6/15/2011	415-030	Concrete Rumble Strips Intersection, Item 415.1180.S: <i>Deleted.</i> This work is now in standard spec 416 under bid item 416.1180, Concrete Rumble Strips Intersection.
6/15/2011	415-065	QMP Concrete Pavement; Incentive Strength Concrete Pavement, Item 415.2000.S: <i>Deleted.</i> This QMP work is now in standard spec sections 701, 710 and 715 with the incentive item 715.0415, Incentive Strength Concrete Pavement under section 715.
6/15/2011	416-005	416-005 Concrete Pavement Continuous Diamond Grinding, Item 416.0905: <i>Deleted.</i> This work will now require writing a SPV article. (Contact Quality Management Section for guidance.)
6/15/2011	416-010	Pavement Dowel Bars Retrofit Warranted, Item 416.0623.S. Updated reference from 415.3.11.8 to 415.3.10.
6/15/2011	416-015	Concrete Pavement Partial Depth Repair Joint Repair, Item 416.0750.S; Crack Repair, Item 416.0752.S; Surface Repair, Item 416.0754.S; Edge Repair, Item 416.0756.S; Full Depth Adjustment, Item 416.0758.S. Updated references from 415.3.17 to 415.3.15 and from 415.3.9 to 415.3.7.

		STSPLOG (Standardized Special Provisions) June 15, 2011 Updates
DATE	PROVISION #	COMMENTS
6/15/2011	460-001	Warranted HMA Pavement Mainline, Item 460.1905.S; Warranted HMA Pavement Ancillary, Item 460.1955.S. Updated distress thresholds, conflict resolution, and other language. Changed the specification to reference pavement condition index, and better define when to use either the 5 or 3 year warranty.
6/15/2011	495-005	Warranted HMA Pavement Overlay Mainline, Item 495.0100.S; Warranted HMA Pavement Overlay Ancillary, Item 495.0200.S. Updated distress thresholds, conflict resolution and other language. Changed the specification to reference pavement condition index and better define when to use either the 5 year or 3 year warranty.
6/15/2011	501-065	QMP Concrete Ancillary: Deleted. This QMP work is now in standard spec sections 701, 710 and 716.
6/15/2011	502-020	Expansion Device, Structure (Number): Updated reference to ASTM standard.
6/15/2011	502-045	QMP Concrete Structures; Incentive Strength Concrete Structures; Item 502.0400.S: Deleted. This QMP work is now in standard spec sections 701, 710 and 715 with the incentive item 715.0502, Incentive Strength Concrete Structures under section 715.
6/15/2011	509-010	Removing Asphaltic Concrete Deck Overlay, Item 509.9010.S: Added (Structure) field to title and bid item description.
6/15/2011	517-040	Painting Epoxy System Structure: Deleted. This work is now in standard spec 517 and is incidental to the 517.0600, Painting Epoxy System (structure) bid item.
6/15/2011	517-150	Architectural Surface Treatment (Structure), Item 517.1050.S: Revised form liner language in first paragraph of B Materials.
6/15/2011	520-015	Culvert Pipe Liners, (Inch), Item 520.0700.S: Added language to section A Description and C.1 Plastic Liners.
6/15/2011	531-005	Noise Barriers Single Sided Sound Absorptive Structure, Item 531.0200.S. Minor revisions throughout.
6/15/2011	531-010	Noise Barriers Double Sided Sound Absorptive Structure, Item 531.0300.S. Minor revisions throughout.
6/15/2011	550-005	Piling (Type) (Size); Piling Precast Concrete Testing; Pile Splices Precast Concrete (Size); Pile Points; Pile Redriving; Pre-Boring (Material Type): Added bid item for Pre-Boring (Consolidated Material) and updated reference to ASTM standard.
6/15/2011	550-010	Piling (Type) (Size); Piling Precast Concrete Testing; Pile Splices Precast Concrete (Size); Pile Points; Pile Redriving; Pre-Boring (Material Type): Updated reference to ASTM standard.
6/15/2011	643-050	Traffic Control Signs Portable Changeable Message, Item 643.1050.S: Deleted. This work is now in standard spec 643 under bid item 643.1050, Traffic Control Signs PCMS.

		STSPLOG (Standardized Special Provisions) June 15, 2011 Updates
DATE	PROVISION #	COMMENTS
6/15/2011	646-010	Pavement Marking Late Season, Item 646.0900.S: <i>New bid item and STSP.</i> Only use on contracts projected to be completed after November 15.
6/15/2011	647-005	Pavement Marking Warranty Bars Epoxy 6-Inch, Item 647.8106.S. <i>New bid item and STSP.</i> Always use with STSP 460-001 and 495-005 on warranty projects to place marks across the centerline to identify warranty projects.
6/15/2011	Plan letter	Plan letter: Edits made throughout.
6/15/2011		Index – With Design Notes – Updated revision dates of STSPs, revised technical notes for STSP 107-200 and 520-015. Added new STSPs NAE1 and E6. Revised date for STSP 107-054 to match STSP date.