

## WisDOT Official List of Qualified Industry and Consultant Laboratories 08/16/2021

Name and Address	Sampling/Testing and Related Activities Performed	Application Date	Effective Date	Expiration Date
<p>All Testing Specialists, LLC* 278 N Main Street Dousman, WI 53118</p> <p>Mark Sweeting <a href="mailto:mark.sweeting@alltestlab.com">mark.sweeting@alltestlab.com</a> 262-695-4942</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, T96, T104, AMRL Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, Asphalt Mix Design (CMM 8-66.2), Extractions (T308 WisDOT Modified), Extraction (T164 Method B), T30, T166, T209, T269, T305, T312, ASTM D2950.</p>	December 1, 2020	January 1, 2021	December 31, 2021
<p>All Testing Specialists, LLC 5423 Reiner Road Sun Prairie, WI 53590</p> <p>Trailer Lab: 1</p> <p>Mark Sweeting <a href="mailto:mark.sweeting@alltestlab.com">mark.sweeting@alltestlab.com</a> 262-695-4942</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Asphalt Mix Design (CMM 8-66.2), Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, ASTM D2950.</p>	December 1, 2020	January 1, 2021	December 31, 2021

<p>American Engineering Testing, Inc. * 550 Cleveland Avenue North St. Paul, MN 55114</p> <p>Chelsea Buck <a href="mailto:cbuck@amengtest.com">cbuck@amengtest.com</a> 218-628-1518</p>	<p>Aggregate: Fracture (Coarse agg.), Permeability (WisDOT Test Method), T11, T27, T84, T85, T255, ASTM D4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Asphalt Mix Design (CMM 8-66.2), Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T305, T312, T331, ASTM D2950.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T198, T231, T277, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D 422, ASTM D 1140.</p>	December 7, 2020	January 1, 2021	December 31, 2021
<p>American Engineering Testing, Inc. * 4203 Schofield Avenue Suite #1 Schofield, WI 54476</p> <p>Paul Michlig <a href="mailto:pmichlig@amengtest.com">pmichlig@amengtest.com</a> 715-359-3545</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, AMRL Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, Asphalt Mix Design (CMM 8-66.2), Extractions (T308 WisDOT Modified), Extractions (T164 Method A), Extractions (T164 Method B), Extractions (ASTM D8159 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T198, T231, T277, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D 422, ASTM D 1140, R58.</p>	December 4, 2020	January 1, 2021	December 31, 2021

<p>American Engineering Testing, Inc. 3194 Market Street, Suite D Green Bay WI 54304</p> <p>Zach Kaup <a href="mailto:zkaup@amengtest.com">zkaup@amengtest.com</a> 920-347-1286</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152-Air Content, T152-Air Meter Calibration, , T198, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D422, ASTM D 1140, R58.</p>	<p>December 16, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>American Engineering Testing, Inc. 1837 CTH OO Chippewa Falls, WI 54729</p> <p>Joel J. Guanella <a href="mailto:JGuanella@amengtest.com">JGuanella@amengtest.com</a> 715-861-5045</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, AMRL Proficiency Sample Program.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T198, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D 422, ASTM D 1140, R58.</p>	<p>December 4, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>A.W. Oakes &amp; Son 9631 Charles St. Sturtevant, WI 53177</p> <p>Jason Andrews <a href="mailto:jandrews@awoakes.com">jandrews@awoakes.com</a> 414-491-8111</p>	<p>Aggregate: WisDOT fracture (coarse), Permeability (WisDOT Test Method), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Concrete Mix: T22, T23, T119, T152, T309, R39, R60.</p>	<p>December 22, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Bacco Construction Company Design Lab N3666 U.S. 2 P O Box 458 Iron Mountain, MI 49801</p> <p>Brian Vuorinen <a href="mailto:brianv@baccocc.com">brianv@baccocc.com</a> 906-774-4064</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Asphalt Mix Design (CMM 8-66.2), Extractions (T308 WisDOT Modified), T30, Extractions (T164 Method A), T166, T209, T269, T305, T312, T331, ASTM D2950.</p>	<p>December 14, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Bacco Construction Company N3666 U.S. 2 P O Box 458 Iron Mountain, MI 49801</p> <p>Trailer Lab #s , 1551</p> <p>Brian Vuorinen <a href="mailto:brianv@baccocc.com">brianv@baccocc.com</a> 906-774-4064</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), Extractions (T164 Method A), T166, T269, T305, T331, ASTM D2950.</p>	<p>December 14, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Bacco Construction Company N3666 U.S. 2 P O Box 458 Iron Mountain, MI 49801</p> <p>Trailer Lab #s , 1555, 1556</p> <p>Brian Vuorinen <a href="mailto:brianv@baccocc.com">brianv@baccocc.com</a> 906-774-4064</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), Asphalt Mix Design (CMM 8-66-2), T30, T166, T209, T312, T305, T331, ASTM D2950.</p>	<p>December 14, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Badgerland Testing Laboratory 11815 County Road Q Two Rivers, WI 54241</p> <p>Thomas Sand <a href="mailto:TSAND@VINTONWIS.COM">TSAND@VINTONWIS.COM</a> 920-973-8942</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T255, ASTM D4791, R76, R90.</p>	<p>December 11, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Barron County Highway Department 260 North 7<sup>th</sup> Street Barron, WI 54812</p> <p>Field Lab #: 319-Z</p> <p>Brent Thill <a href="mailto:Sandra.perry@co.barron.wi.us">Sandra.perry@co.barron.wi.us</a> 715-637-3755</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T255, R76, R90.</p>	<p>December 31, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Bay Area Testing and Consulting, LLC 3125 Birch Road Suite B Suamico, WI 54173</p> <p>Jake Franzmeier <a href="mailto:jake@bayareateesting.com">jake@bayareateesting.com</a> 920-660-5246</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, ASTM D 4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (ASTM D8159 WisDOT Modified), T30, ASTM D2950.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T198, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D422, ASTM D 1140.</p>	<p>December 23, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Behnke Materials Engineering, LLC* 1209 E Elmwood Ave, Unit B Beloit, WI 53511</p> <p>Josh Amundson <a href="mailto:jjamundson@behnkematerialsengineering.com">jjamundson@behnkematerialsengineering.com</a> 608-713-4523</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T85, T84, T96, T103, T104, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, Asphalt Mix Design (CMM 8-66.2), Extractions (ASTM 8159 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D 1140.</p>	<p>December 30, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Bitumix Solutions, a Div. of H.G. Meigs, LLC* 1220 Superior St. Portage, WI 53901</p> <p>Dan Swiertz <a href="mailto:dswiertz@bitumixsolutions.com">dswiertz@bitumixsolutions.com</a> 262-483-7182</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T84, T85, T255, ASTM D 4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Asphalt Mix Design (CMM 8-66.2), Extractions (T308 WisDOT Modified), Extractions (T164 Method A), T30, T166, T209, T269, T312.</p>	<p>December 16, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Bjoin Limestone Inc. 7308 W. State Rd. 11 Janesville, WI 53548</p> <p>Daniel Jones <a href="mailto:dan@bjoinlimestone.com">dan@bjoinlimestone.com</a> 608-876-6959</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability (wisDOT Test Method), T11, T27, ASTM D4791, R76, R90.</p>	<p>January 7, 2021</p>	<p>January 7, 2021</p>	<p>December 31, 2021</p>

<p>Blaine's Concrete Testing, LLC 1622 South 89<sup>th</sup> Street West Allis, WI 53214</p> <p>James Blaine <a href="mailto:jim@blainestesting.com">jim@blainestesting.com</a> 414-412-5424</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Concrete Mix: T22, T23, T119, T152, T309, R39, R60.</p>	<p>December 10, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Bowser- Morner, Inc. * 4518 Taylorsville Road, Dayton, OH 45424</p> <p>Karl A. Fletcher, Laboratory Manager <a href="mailto:kfletcher@bowser-morner.com">kfletcher@bowser-morner.com</a> 937-236-8805</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, T96, T104, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: T30, Extractions (T164 Method A), Extractions (T164 Method B), T166, T209, T269.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T198, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D 422, ASTM D 1140, R58.</p>	<p>December 9, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Bowser- Morner, Inc. * 1419 Miami Street Toledo, OH 43605</p> <p>Thomas Weaver, Laboratory Manager <a href="mailto:tweaver@bowser-morner.com">tweaver@bowser-morner.com</a> 419-691-4800</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, R76, R90.</p> <p>Asphalt Mix: T30, T166, T209, T269, Extractions (T164 Method A), Extractions (Method B), .</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D 422, ASTM D-1140, R58.</p>	<p>December 9, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Braun Intertec Corporation * 11001 Hampshire Avenue South Bloomington, MN 55438</p> <p>Josh Kylander <a href="mailto:jkylander@braunintertec.com">jkylander@braunintertec.com</a> 952-995-2000</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, T96, T104.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, ASTM D 422, ASTM D 1140, R58.</p>	<p>January 4, 2021</p>	<p>January 4, 2021</p>	<p>December 31, 2021</p>
<p>Braun Intertec Corporation * 2309 Palace St. La Crosse, WI 54603</p> <p>Benjamin Sullivan <a href="mailto:bsullivan@braunintertec.com">bsullivan@braunintertec.com</a> 608-781-7277</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Asphalt Mix: T166, ASTM D2950.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T231, T309, R60.</p> <p>Soils: T88, T89, T90, T99, T180, T265, T310, ASTM D422, ASTM D 1140, R58.</p>	<p>December 4, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Cedar Lake Sand &amp; Gravel Inc. 5189 Aurora Rd. Hartford, WI 53027</p> <p>Patrick Strachan <a href="mailto:robert@cedarlakesand.com">robert@cedarlakesand.com</a> 262-644-5125</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T89, T90, ASTM D4791, R76, R90.</p>	<p>December 2, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>



<p>Cemstone Ready Mix 1190 County Road G New Richmond, WI 54017</p> <p>Jake Ostendorf <a href="mailto:jostendorf@cemstone.com">jostendorf@cemstone.com</a> 715-441-7373</p>	<p>Aggregate: T11, T27, T255, R90.</p> <p>Concrete Mix: T22, T23, T119, T152, T309, R39, R60.</p>	<p>December 7, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Central State Construction, LLC 804 Superior Ave. Suite A Tomah, WI 54660</p> <p>William Kobleska <a href="mailto:whk@centralstateconstructionllc.com">whk@centralstateconstructionllc.com</a> 608-547-2214</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Soils: T88, T89, T90, T265, ASTM D1140.</p>	<p>December 18, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>CGC, Inc. * 2921 Perry Street Madison, WI 53713</p> <p>Mark Skau <a href="mailto:mskau@cgcinc.net">mskau@cgcinc.net</a> 608-288-4100</p>	<p>Aggregate: Fracture (Coarse agg.), Permeability (WisDOT Test Method), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74, T84, T85, T96, T104, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), Extractions (T164 Method A), T30, T166, T209, T269, T312, T331, ASTM D2950.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T198, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T100, T180, T265, T310, ASTM D-422, ASTM D-1140.</p>	<p>December 16, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>CGC, Inc. 336 S. Curtis Rd. West Allis, WI 53214</p> <p>Jeff Simkowski <a href="mailto:jsimkowski@cgcinc.net">jsimkowski@cgcinc.net</a> 414-443-2000</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T89, T90, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, ASTM D2950.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T180, T265, T310, ASTM D422, ASTM D1140.</p>	December 16, 2020	January 1, 2021	December 31, 2021
<p>Chippewa Concrete Mobile Lab 1 3030 110th Street Chippewa Falls, WI 54729</p> <p>Charlie McCall <a href="mailto:charlie@chippewaconcrete.net">charlie@chippewaconcrete.net</a> 715-723-5004</p>	<p>Aggregate: Permeability (WisDOT Test Method), T11, T27, T85, T255, R76, R90.</p> <p>Concrete Mix: T22, T23, T97, T119, T152-Air Content, T152-Air Meter Calibration, T309, R39.</p>	December 4, 2020	January 1, 2021	December 31, 2021
<p>Chippewa Concrete Mobile Lab 2 3030 110th Chippewa Falls, WI 54729</p> <p>Charlie McCall <a href="mailto:charlie@chippewaconcrete.net">charlie@chippewaconcrete.net</a> 715-723-5004</p>	<p>Aggregate: Permeability (WisDOT Test Method), T11, T27, T85, T255, R76, R90.</p> <p>Concrete Mix: T22, T23, T97, T119, T152-Air Content, T152, Air Meter Calibration, T309, R39.</p>	December 4, 2020	January 1, 2021	December 31, 2021
<p>Chippewa Concrete 11320 30<sup>th</sup> Avenue Chippewa Falls, WI 54729</p> <p>Permanent Lab</p> <p>Charlie McCall <a href="mailto:charlie@chippewaconcrete.net">charlie@chippewaconcrete.net</a> 715-723-5004</p>	<p>Aggregate: Permeability (WisDOT Test Method), T11, T27, T85, T255, R76, R90.</p> <p>Concrete Mix: T22, T23, T97, T119, T152-Air Content, T152, Air Meter Calibration, T309, R39.</p>	December 4, 2020	January 1, 2021	December 31, 2021

<p>Chosen Valley Testing * 1019 2<sup>nd</sup> Ave SW Onalaska, WI 54650</p> <p>Kraig McCoy <a href="mailto:kmccoy@cvtesting.com">kmccoy@cvtesting.com</a> 608-782-5505</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, AMRL's Proficiency Sample Program.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T180, T265, T310, ASTM D422, ASTM D1140, R58.</p>	<p>February 19, 2021</p>	<p>February 19, 2021</p>	<p>December 31, 2021</p>
<p>Coleman Engineering Company 200 E. Ayer Street Ironwood, MI 49938</p> <p>Garth Stengard <a href="mailto:gstengard@coleman-engineering.com">gstengard@coleman-engineering.com</a> 906-932-5048</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Asphalt Mix: ASTM D2950.</p> <p>Concrete Mix: T22, T23, T97, T119, T152, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D 422, ASTM D 1140, R58.</p>	<p>December 4, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Coleman Engineering Company* 635 Circle Drive Iron Mountain, MI 49801</p> <p>Jeanne Johnson <a href="mailto:jjohnson@coleman-engineering.com">jjohnson@coleman-engineering.com</a> 906-774-3440</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T85, T84, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T166, T209, T269, ASTM D2950.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D 422, ASTM D 1140, R58.</p>	<p>December 11, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Cooper Engineering Company, Inc. 2600 College Drive Rice Lake, WI 54868-0230</p> <p>Catherine Isaacson-Larson <a href="mailto:cisaacson-larson@cooperengineering.net">cisaacson-larson@cooperengineering.net</a> 715-234-7008</p>	<p>Aggregate: WISDOT fracture (coarse), T27, T85, T89, T90, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, T166, T209, T269, T331, ASTM D2950.</p> <p>Concrete Mix: T22, T23, T119, T152-Air Content, T152-Air Meter Calibration, T231, T309, R60.</p> <p>Soils: T88, T89, T90, T99, T180, T265, T310, ASTM D 422, ASTM D 1140.</p>	February 24, 2021	February 24, 2021	December 31, 2021
<p>Cornerstone Cylinder Breaker 6422 N. Hwy 31 Racine, WI 53402</p> <p>Mobile Lab</p> <p>Christopher Cape <a href="mailto:ccape@cornerstonepersusa.com">ccape@cornerstonepersusa.com</a> 262-456-0430</p>	Concrete Mix: T22	May 20, 2021	May 20, 2021	December 31, 2021
<p>CORRE, Inc. 175 E. Wisconsin Avenue Suite 27 Oconomowoc, WI 53066</p> <p>Field Lab</p> <p>Joel Weber <a href="mailto:jweber@correinc.com">jweber@correinc.com</a> 715-213-9337</p>	Concrete Mix: T23, T119, T152, T309, R60.	December 8, 2020	January 1, 2021	December 31, 2021
<p>County Materials Corporation -- Holmen 120 Union Street Holmen, WI 54636</p> <p>Mike Ostrem <a href="mailto:Mike.ostrem@countymaterials.com">Mike.ostrem@countymaterials.com</a> 608-526-1065</p>	Concrete Mix: T22, T23, T119, T152-Air Content, T152-Aggregate Correction (air) WisDOT Modified, T309, R39.	December 8, 2020	January 1, 2021	December 31, 2021

<p>County Materials Corporation 205 North Street Marathon, WI 54448</p> <p>Mike Strong <a href="mailto:mike.strong@countymaterials.com">mike.strong@countymaterials.com</a> 715-551-8259</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, AMRL's Proficiency Sample Program.</p> <p>Concrete Mix: T22, T23, T119, T152, T309, R39, R60.</p>	December 8, 2020	January 1, 2021	December 31, 2021
<p>County Materials Corporation 1203 70<sup>th</sup> Ave. Roberts, WI 54023</p> <p>Wayne M. Flick <a href="mailto:Wayne.flick@countymaterials.com">Wayne.flick@countymaterials.com</a> 715-749-2274</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Concrete Mix: T22, T23, T119, T152-Air Content, T152-Air Meter Calibration, T309, R39, R60.</p>	December 8, 2020	January 1, 2021	December 31, 2021
<p>County Materials - Trempealeau W21512 11<sup>th</sup> St. Trempealeau, WI 54661</p> <p>Mike Ostrem <a href="mailto:Mike.ostrem@countymaterials.com">Mike.ostrem@countymaterials.com</a> 608-534-7425</p>	<p>Aggregate: T11, T27, T255, R90.</p>	December 8, 2020	January 1, 2021	December 31, 2021
<p>CRM Laboratory 1725 Gillette Place La Crosse, WI 54603</p> <p>Brad Rugg <a href="mailto:Brad.rugg@croell.com">Brad.rugg@croell.com</a> 608-781-3200</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Concrete Mix: T22, T23, T119, T152, T231, T309, R39, R60.</p>	January 7, 2021	January 7, 2021	December 31, 2021

<p>DAAR Engineering, Inc. 151 East Cook Street Portage, WI 53901</p> <p>Daulton Valleskey <a href="mailto:Daulton.valleskey@daarcorp.com">Daulton.valleskey@daarcorp.com</a> 262-468-7485</p>	<p>Aggregate: R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, ASTM D2950</p> <p>Concrete Mix: T23, T119, T152-Air Content, T152-Air Meter Calibration, T309, R60.</p> <p>Soils: T310.</p>	<p>November 24, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Dyersville Ready Mix Inc. DBA Bard Materials * 2400 Hwy 52 South Dubuque, IA 52003</p> <p>Brian Luchene <a href="mailto:brianl@bardmaterials.com">brianl@bardmaterials.com</a> 563-875-5068</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T84, T85, T255, ASTM D4791, R76, R90.</p> <p>Concrete Mix: T22, T23, T119, T152, R39, R60.</p>	<p>December 14, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>ECS Midwest, LLC * 1280 Parkview Road Green Bay, WI 54304</p> <p>Lab # 59</p> <p>Troy Vetort, P.E. <a href="mailto:tvetort@ecslimited.com">tvetort@ecslimited.com</a> 920-347-9040</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, T96, T103, T104.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T198, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D 422, ASTM D 1140, R58.</p>	<p>January 12, 2021</p>	<p>January 12, 2021</p>	<p>December 31, 2021</p>

<p>ECS Midwest Neenah Lab 1060 Breezewood Lane Neenah, WI 54956</p> <p>Timothy Hendrickson/Nick Porter <a href="mailto:thendrickson@ecslimited.com">thendrickson@ecslimited.com</a> 920-886-1406</p>	<p>Aggregate: T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), Extractions (T164 Method A), Extractions (T164 Method B), Extractions (ASTM D8159 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p> <p>Concrete Mix: T22, T23, T119, T152, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D 422, ASTM D 1140, R58.</p>	<p>December 21, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Evenson Construction Company Inc. 4915 County Road A Valders, WI 54245</p> <p>Andrew L Niemuth <a href="mailto:andy@evensonconstruction.com">andy@evensonconstruction.com</a> 920-775-4652</p>	<p>Aggregate: WisDOT Fracture (Coarse), T11, T27, T90, ASTM D4791, R76, R90.</p>	<p>December 8, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Faulks Bros. Construction, Inc. E3481 Royalton St. Waupaca, WI 54981</p> <p>Mark J. Weinreis <a href="mailto:mark@waupacasand.com">mark@waupacasand.com</a> 715-258-8566</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T255, ASTM D4791, R76, R90.</p>	<p>December 8, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>GeoTest, Inc. 2135 S. 116th Street West Allis, WI 53227</p> <p>Michael J. Markgraf, P.G. <a href="mailto:mmarkgraf@888geotest.com">mmarkgraf@888geotest.com</a> 414-343-6207</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability (WisDOT Test Method), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, AMRL's Proficiency Sample Program.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T198, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D 422, ASTM D 1140, R58.</p>	December 10, 2020	January 1, 2021	December 31, 2021
<p>GeoTest, Inc. 686 Progress Way, Unit 4 Sun Prairie, WI 53590</p> <p>Michael J. Markgraf, P.G. <a href="mailto:mmarkgraf@888geotest.com">mmarkgraf@888geotest.com</a> 414-343-6207</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T255, R76, R90.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T309, R39, R60.</p> <p>Soils: T88, T99, T180, T265, T310, ASTM D 1140, R58.</p>	December 10, 2020	January 1, 2021	December 31, 2021
<p>Gestra Engineering, Inc. * 191 W. Edgerton Ave. Milwaukee, WI 53207</p> <p>Thomas Stevens <a href="mailto:Thomas.anderson@gestrainc.com">Thomas.anderson@gestrainc.com</a> 414-933-7444</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability (WisDOT Test Method), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T96, T104.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T198, T231, T277, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D 422, ASTM D 1140, R58.</p>	December 4, 2020	January 1, 2021	December 31, 2021



<p>Gestra Engineering, Inc. 2975 Kapec Rd. Madison WI 53719</p> <p>Trailer Lab</p> <p>Shane Savin <a href="mailto:Shane.savin@gestrainc.com">Shane.savin@gestrainc.com</a> 414-933-7444</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T89, T90, T255, R76, R90.</p> <p>Concrete Mix: T22, T24, T119, T152-Air Content, T198, T231.</p> <p>Soils: T88, T89, T90, T99, T180, T265, T310, ASTM D 422, ASTM D 1140, R58.</p>	<p>February 24, 2021</p>	<p>February 24, 2021</p>	<p>December 31, 2021</p>
<p>Gestra Engineering, Inc. 2223 Industrial Drive Monona, WI 53713</p> <p>Thomas Stevens <a href="mailto:Thomas.anderson@gestrainc.com">Thomas.anderson@gestrainc.com</a> 414-234-9112</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T89, T90, T255, R76, R90.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T198, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T180, T265, T310, ASTM D 422, ASTM D 1140, R58.</p>	<p>April 9, 2021</p>	<p>April 9, 2021</p>	<p>December 31, 2021</p>
<p>Giles Engineering Associates, Inc. * N8 W22350 Johnson Drive Suite A1 Waukesha, WI 53186</p> <p>Steve Homar, P.E. <a href="mailto:shomar@gilesengr.com">shomar@gilesengr.com</a> 262-544-0118</p>	<p>Aggregate: Fracture (Coarse agg.), Permeability (WisDOT Test Method), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, AMRL Proficiency Sample Program.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T198, T231, T277, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D422, ASTM D 1140, R58.</p>	<p>December 31, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Gremmer &amp; Associates, Inc. 120 Wilshire Boulevard North Stevens Point, WI 54481</p> <p>Scott A. Hintz, P.E., RSO <a href="mailto:s.hintz@gremmerassociates.com">s.hintz@gremmerassociates.com</a> 715-341-4363</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T255, R76, R90.</p> <p>Concrete Mix: T23, T152-Air Content, T152-Air Meter Calibration, T309, R60.</p>	<p>January 21, 2021</p>	<p>January 21, 2021</p>	<p>December 31, 2021</p>
<p>HAAS 3858 County Rd. T Eau Claire, WI 54703</p> <p>Richie Olichwier <a href="mailto:Richie@haas4.com">Richie@haas4.com</a> 715-331-4423</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability (WisDOT Test Method), T11, T27, T84, T85, T90, T255, ASTM D4791, R76, R90.</p> <p>Concrete Mix: T22, T23, T97, T119, T152, T198, T231, T309, R39, R60.</p>	<p>December 4, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Hoffman Construction Company 3802 Evan Acres Rd. Madison, WI 53718</p> <p>Field Lab #: B17</p> <p>Ray Fliflet <a href="mailto:rfliflet@hoffcons.com">rfliflet@hoffcons.com</a> 715-314-0372</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T90, T255, ASTM D4791, R76, R90.</p> <p>Soils: T90, T180.</p>	<p>December 9, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Independence Ready Mix N35178 State Rd. 93 South Independence, WI 54747</p> <p>Mike Kupka <a href="mailto:mkupka@kohnermaterials.com">mkupka@kohnermaterials.com</a> 715-985-3118</p>	<p>Aggregate: T11, T27, T255.</p> <p>Concrete Mix: T23, T119, T152-Air Content, T309, R60.</p>	<p>December 7, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>INTERRA, Inc. 5004 W Ashland Way Franklin, WI 53132</p> <p>Anshuman Balekai <a href="mailto:abalekai@interraservices.com">abalekai@interraservices.com</a> 630-675-1355</p>	<p>Aggregate: T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, ASTM D2950.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T198, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D 422, ASTM D 1140, R58.</p>	<p>December 18, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>INTERRA, Inc. * 600 Territorial Drive, Suite G Bolingbrook, IL 60440</p> <p>Anshuman Balekai <a href="mailto:abalekai@interraservices.com">abalekai@interraservices.com</a> 630-675-1355</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability (WisDOT Test Method), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, ASTM D2950.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T198, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D 422, ASTM D 1140, R58.</p>	<p>December 18, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>James Peterson Sons, Inc. N2251 Gibson Drive Medford, WI 54451</p> <p>Field Lab I</p> <p>Brett Machon <a href="mailto:Brett.machon@jpsbp.com">Brett.machon@jpsbp.com</a> 715-748-1271</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T90, T255, R76, R90, ASTM D4791.</p>	<p>January 22, 2021</p>	<p>January 22, 2021</p>	<p>December 31, 2021</p>

<p>James Peterson Sons, Inc. (Lab II) N2251 Gibson Drive Medford, WI 54451</p> <p>Field Lab II</p> <p>Brett Machon <a href="mailto:Brett.machon@jpsbp.com">Brett.machon@jpsbp.com</a> 715-748-1271</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T90, T255, R76, R90, ASTM D4791.</p>	<p>January 22, 2021</p>	<p>January 22, 2021</p>	<p>December 31, 2021</p>
<p>Jewell Associates Engineers, Inc. 560 Sunrise Drive Spring Green, WI 53588</p> <p>Ralph J. Liegel <a href="mailto:Ralph.liegel@jewellassoc.com">Ralph.liegel@jewellassoc.com</a> 608-588-7484</p>	<p>Aggregate: R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, ASTM D2950.</p> <p>Concrete Mix: T23, T119, T152-Air Content, T152-Air Meter Calibration, T309, R60.</p>	<p>December 7, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>John S Olynick Inc. N7918 Hwy 73 Gilman, WI 54433</p> <p>Jacque Ludescher <a href="mailto:olynick@centurytel.net">olynick@centurytel.net</a> 715-668-5211</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T255, R76, R90.</p> <p>Concrete Mix: T119, T152-Air Content, T152-Air Meter Calibration, T309, R60.</p>	<p>December 9, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Kapur &amp; Associates, Inc. 10101 Market St.; Suite C20 Rothschild, WI 54474</p> <p>Jason G. Hassler <a href="mailto:jhassler@kapur-assoc.com">jhassler@kapur-assoc.com</a> 715-584-3300</p>	<p>Aggregate: R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, ASTM D2950.</p> <p>Concrete Mix: T23, T119, T152-Air Content, T152-Air Meter Calibration, T309, R60.</p> <p>Soils: T310.</p>	<p>December 21, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>KL Engineering, Inc. 5400 King James Way Suite 200 Madison, WI 54719</p> <p>Lab #1</p> <p>Joseph Jirsa <a href="mailto:jjirsa@klengineering.com">jjirsa@klengineering.com</a> 608-663-1218</p>	<p>Aggregate: R90.</p> <p>Asphalt Mix: ASTM D2950.</p> <p>Concrete Mix: T23, T119, T152-Air Content, T309, R60.</p>	<p>December 7, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>KL Engineering, Inc. 393 Red Cedar Street, Suite 2 Menomonie, WI 54751</p> <p>Lab #2</p> <p>Chris Ehlert <a href="mailto:cehlert@klengineering.com">cehlert@klengineering.com</a> 715-231-1600</p>	<p>Aggregate: R90.</p> <p>Asphalt Mix: ASTM D2950.</p> <p>Concrete Mix: T23, T119, T152-Air Content, T309, R60.</p>	<p>December 7, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>KL Engineering, Inc. 3040 Allied Street, Suite B Green Bay, WI 54304</p> <p>Lab #3</p> <p>Brett Vissers <a href="mailto:bvissers@klengineering.com">bvissers@klengineering.com</a> 920-347-1218</p>	<p>Aggregate: R90.</p> <p>Asphalt Mix: ASTM D2950.</p> <p>Concrete Mix: T23, T119, T152-Air Content, T309, R60.</p>	<p>December 7, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Kopplin &amp; Kinase Co., Inc. W1266 N Lawson Dr. Green Lake, WI 54941</p> <p>Trailer Lab</p> <p>Michael C McConnell <a href="mailto:mmc@kkci.us">mmc@kkci.us</a> 920-294-6451</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T89, T90, T255, ASTM D4791, R76, R90.</p>	<p>December 28, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>The Kraemer Company, LLC 820 Wachter Avenue Plain, WI 53577</p> <p>Mark Sander <a href="mailto:marks@tkcllc.com">marks@tkcllc.com</a> 608-546-2255X2204</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T85, T96, T96, T103, T104, AMRL's Proficiency Sample Program.</p>	December 11, 2020	January 1, 2021	December 31, 2021
<p>The Kraemer Company, LLC Elmwood Lab 800 South Public Street Elmwood, WI 54740</p> <p>Mark Sander <a href="mailto:marks@tkcllc.com">marks@tkcllc.com</a> 608-546-2255</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T255, ASTM D4791, R76, R90.</p>	December 11, 2020	January 1, 2021	December 31, 2021
<p>The Kraemer Company, LLC - Arcadia N25355 State Highway 93 Arcadia, WI 54612</p> <p>Mark Sander <a href="mailto:marks@tkcllc.com">marks@tkcllc.com</a> 608-546-2255</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T255, ASTM D4791, R76, R90.</p>	December 11, 2020	January 1, 2021	December 31, 2021
<p>The Kraemer Company, LLC Mollett Lab E8012 State Highway 56 Viroqua, WI 54665</p> <p>Mark Sander <a href="mailto:marks@tkcllc.com">marks@tkcllc.com</a> 608-546-2255</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T255, ASTM D4791, R76, R90.</p>	December 11, 2020	January 1, 2021	December 31, 2021

<p>The Kraemer Company, LLC Williams Lab W11825 US 33 Portage, WI 53901</p> <p>Mark Sander <a href="mailto:marks@tkcllc.com">marks@tkcllc.com</a> 608-546-2255</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T255, ASTM D4791, R76, R90.</p>	<p>December 11, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>The Kraemer Company, LLC 12103 S. Bill Ramel Road Solon Springs, WI 54873</p> <p>Trailer #7679</p> <p>Mark Sander <a href="mailto:marks@tkcllc.com">marks@tkcllc.com</a> 608-546-2255</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T255, ASTM D4791, R76, R90.</p>	<p>December 11, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>The Kraemer Company, LLC 820 Wachter Avenue Plain, WI 53577</p> <p>Trailer Lab #7862</p> <p>Mark Sander <a href="mailto:marks@tkcllc.com">marks@tkcllc.com</a> 608-546-2255X2204</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T255, ASTM D4791, R76, R90.</p>	<p>December 11, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Lafarge Aggregates W249N9436 Hillside Rd Colgate WI 53017</p> <p>Adam Lester <a href="mailto:Adam.Lester@lafargeholcim.com">Adam.Lester@lafargeholcim.com</a> 262-525-1962</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability (WisDOT Test Method), T11, T27, T255, ASTM D4791, R76, R90.</p>	<p>December 29, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Langlade County HWY Dept. 1521 Arctic Street Antigo, WI 54409-2399</p> <p>Field Lab</p> <p>Brian Braun <a href="mailto:bbraun@co.langlade.wi.us">bbraun@co.langlade.wi.us</a> 715-627-6272</p>	<p>Aggregate: Fracture (Coarse Agg.), T11, T27, T255, ASTM D4791, R76.</p> <p>Soils: T88.</p>	<p>March 29, 2021</p>	<p>March 29, 2021</p>	<p>December 31, 2021</p>
<p>LANNON STONE PRODUCTS Lisbon Pit W220N6799 Townline Rd. Sussex, WI 53089</p> <p>Logan T. Shihata <a href="mailto:logans@lannonstone.net">logans@lannonstone.net</a> 608-412-3396</p>	<p>Aggregate: Fracture (Coarse Agg.), T11, T27, T255, ASTM D4791, R76, R90.</p>	<p>January 6, 2021</p>	<p>January 6, 2021</p>	<p>December 31, 2021</p>
<p>LANNON STONE PRODUCTS Sussex Quarry N52W23096 Lisbon Rd Sussex, WI 53089</p> <p>Logan T. Shihata <a href="mailto:logans@lannonstone.net">logans@lannonstone.net</a> 608-412-3396</p>	<p>Aggregate: Fracture (Coarse Agg.), T11, T27, T255, ASTM D4791, R76, R90.</p>	<p>January 6, 2021</p>	<p>January 6, 2021</p>	<p>December 31, 2021</p>



<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Derek Fredrixon <a href="mailto:Derek.Fredrixon@mathy.com">Derek.Fredrixon@mathy.com</a> 715-779-6536</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, T96, T103, T104, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, Asphalt Mix Design (CMM 8-66.2), Extractions (T308 WisDOT Modified), Extractions (T164 Method A), Extractions (T164 Method B), Extractions (ASTM D8159 WisDOT Modified), T30, T166, T209, T269, T305, T312, T331, ASTM D2950.</p> <p>Soils: T88, T89, T90, T99, T180, T265, ASTM D422, ASTM D 1140, R58.</p>	December 15, 2020	January 1, 2021	December 31, 2021
<p>Mathy Construction Co. – Arnot QC Lab 4807 Custer Road Arnot, WI 54480</p> <p>Derek Fredrixon <a href="mailto:Plant83Lab@Mathy.com">Plant83Lab@Mathy.com</a> 715-341-1953</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), Extractions (T164 Method A), Extractions (T164 Method B), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	December 16, 2020	January 1, 2021	December 31, 2021
<p>Mathy Construction Co.–Browns Bottom QC Lab 12567 English Mill Road Dubuque, IA 52001</p> <p>Derek Fredrixon <a href="mailto:Plt1QC@Mathy.com">Plt1QC@Mathy.com</a> 563-583-1902</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	December 16, 2020	January 1, 2021	December 31, 2021

<p>Mathy Construction Co. – Fox Ridge QC Lab S5383 US Hwy 12 Baraboo, WI 54913</p> <p>Derek Fredrixon <a href="mailto:Plant65Lab@Mathy.com">Plant65Lab@Mathy.com</a> 608-356-3742</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T90, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	December 16, 2020	January 1, 2021	December 31, 2021
<p>Mathy Construction Co. – New Richmond QC Lab 1190 County Road G New Richmond, WI 54017</p> <p>Derek Fredrixon <a href="mailto:Plant59Lab@Mathy.com">Plant59Lab@Mathy.com</a> 715-246-7019</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), Extractions (T164 Method A), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	December 16, 2020	January 1, 2021	December 31, 2021
<p>Mathy Construction Co. – PL 41 Superior QC Lab 5927 Albany Avenue Superior, WI 54880</p> <p>Derek Fredrixon <a href="mailto:Plant41Lab@Mathy.com">Plant41Lab@Mathy.com</a> 715-392-1989</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), Extractions (T164 Method A), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	December 16, 2020	January 1, 2021	December 31, 2021
<p>Mathy Construction Co. – Plant 87 QC Lab W5380 State Hwy 85 Eau Claire, WI 54701</p> <p>Derek Fredrixon <a href="mailto:Plant87Lab@Mathy.com">Plant87Lab@Mathy.com</a> 715-835-0167</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), Extractions (T164 Method A), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	December 16, 2020	January 1, 2021	December 31, 2021

<p>Mathy Construction Company  AMC Pit 31 QC Lab  3289 Jopke Road  Eau Claire, WI 54702</p> <p>Derek Fredrixon  <a href="mailto:ervin.dukat@mathy.com">ervin.dukat@mathy.com</a>  715-830-2251</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Concrete: T22, T23, T24, T97, T119, T152, T198, T309, R39, R60.</p>	<p>December 16, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company  Ashland QC Lab  50660 State Road 112  Ashland, WI 54806</p> <p>Derek Fredrixon  <a href="mailto:Ervin.Dukat@mathy.com">Ervin.Dukat@mathy.com</a>  715-685-9525</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p>	<p>December 16, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company  Hayward QC Lab  11154 N. Olson Road  Hayward, WI 54843</p> <p>Derek Fredrixon  <a href="mailto:ervin.dukat@mathy.com">ervin.dukat@mathy.com</a>  715-234-2626</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Concrete: T22, T23, T24, T119, T152, T309, R39, R60.</p>	<p>December 16, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Co. Plant 86 QC Lab  2601 Conoco Road  La Crosse WI 54601</p> <p>Derek Fredrixon  <a href="mailto:PLT86LAB@Mathy.com">PLT86LAB@Mathy.com</a>  608-779-6687</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 16, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Mathy Construction Company Mosinee QC Lab 1050 Happy Hollow Road Mosinee, WI 54455</p> <p>Derek Fredrixon <a href="mailto:Plant22Lab@Mathy.com">Plant22Lab@Mathy.com</a> 715-693-5279</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Asphalt Mix Design (CMM 8-66.2), Extractions (T308 WisDOT Modified), Extractions (ASTM D8159 WisDOT Modified), T30, T166, T209, T269, T305, T312, T331, ASTM D2950.</p>	<p>December 15, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company Amery QC Lab 768 US Hwy 8 Amery, WI 54001</p> <p>Derek Fredrixon <a href="mailto:Plant5Lab@Mathy.com">Plant5Lab@Mathy.com</a> 715-268-2687</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Asphalt Mix Design (CMM 8-66.2), Extractions (T308 WisDOT Modified), Extractions (T164 Method A), Extractions (T164 Method B), T30, T166, T209, T269, T305, T312, T331, ASTM D2950.</p>	<p>December 15, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable QC Lab Trailers: # 44-28</p> <p>Derek Fredrixon <a href="mailto:Lab44-28@Mathy.com">Lab44-28@Mathy.com</a> 608-779-4826</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), Extractions (T164 Method A), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable QC Lab: # 44-29</p> <p>Derek Fredrixon <a href="mailto:Lab44-29@Mathy.com">Lab44-29@Mathy.com</a> 608-799-4831</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable QC Lab: # 44-42</p> <p>Derek Fredrixon <a href="mailto:Ervin.Dukatz@Mathy.com">Ervin.Dukatz@Mathy.com</a> 715-234-2626</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p>	<p>December 16, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable QC Lab Trailers: # 44-46</p> <p>Derek Fredrixon <a href="mailto:Lab44-46@Mathy.com">Lab44-46@Mathy.com</a> 608-799-6515</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable QC Lab Trailers: # 44-62</p> <p>Derek Fredrixon <a href="mailto:Lab44-62@Mathy.com">Lab44-62@Mathy.com</a> 608-799-5623</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable QC Lab Trailers: # 44-63</p> <p>Derek Fredrixon <a href="mailto:Lab44-63@Mathy.com">Lab44-63@Mathy.com</a> 608-799-5704</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Mathy Construction Company W7378 STH 95 Neillsville, WI 54456</p> <p>Merrillan QC Lab # 44-99.</p> <p>Derek Fredrixon <a href="mailto:Lab44-99@Mathy.com">Lab44-99@Mathy.com</a> 608-799-5836</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p>	<p>December 16, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable QC Lab Trailers: # 44-112</p> <p>Derek Fredrixon <a href="mailto:Lab44-112@Mathy.com">Lab44-112@Mathy.com</a> 608-799-4774</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable QC Lab Trailers: # 44-135</p> <p>Derek Fredrixon <a href="mailto:Lab44-135@Mathy.com">Lab44-135@Mathy.com</a> 608-799-4786</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable QC Lab Trailers: # 44-152</p> <p>Derek Fredrixon <a href="mailto:Lab44-152@Mathy.com">Lab44-152@Mathy.com</a> 608-799-4816</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable QC Lab Trailers: # 44-155</p> <p>Derek Fredrixon <a href="mailto:Lab44-155@Mathy.com">Lab44-155@Mathy.com</a> 608-799-4822</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable QC Lab Trailer: # 44-164.</p> <p>Derek Fredrixon <a href="mailto:Lab44-164@Mathy.com">Lab44-164@Mathy.com</a> 608-780-4279</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p>	<p>December 16, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable QC Lab Trailers: # 44-166</p> <p>Derek Fredrixon <a href="mailto:Lab44-166@Mathy.com">Lab44-166@Mathy.com</a> 608-799-5849</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable QC Lab Trailers: # 44-168</p> <p>Derek Fredrixon <a href="mailto:Lab44-168@Mathy.com">Lab44-168@Mathy.com</a> 608-799-5086</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable QC Lab Trailers: # 44-170</p> <p>Derek Fredrixon <a href="mailto:Lab44-170@Mathy.com">Lab44-170@Mathy.com</a> 608-799-5040</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable QC Lab Trailer: # 44-176.</p> <p>Derek Fredrixon <a href="mailto:Lab44-176@Mathy.com">Lab44-176@Mathy.com</a> 608-799-4876</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable Lab Trailer: # 44-177.</p> <p>Derek Fredrixon <a href="mailto:Lab44-177@Mathy.com">Lab44-177@Mathy.com</a> 608-799-2465</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331 ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable Lab Trailer: # 44-178.</p> <p>Derek Fredrixon <a href="mailto:Lab44-178@Mathy.com">Lab44-178@Mathy.com</a> 608-799-2564</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>



<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable Lab Trailer: # 44-180</p> <p>Derek Fredrixon <a href="mailto:Lab44-180@Mathy.com">Lab44-180@Mathy.com</a> 608-769-8230</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable Lab Trailer: # 44-182</p> <p>Derek Fredrixon <a href="mailto:Lab44-180@Mathy.com">Lab44-180@Mathy.com</a> 608-518-2433</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Trailer Lab #44-184</p> <p>Derek Fredrixon <a href="mailto:Lab44-184@Mathy.com">Lab44-184@Mathy.com</a> 608-799-2666</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T85, T255, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Trailer Lab #44-185</p> <p>Derek Fredrixon <a href="mailto:Lab44-185@Mathy.com">Lab44-185@Mathy.com</a> 608-799-4854</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Trailer Lab #44-186</p> <p>Derek Fredrixon <a href="mailto:Lab44-186@Mathy.com">Lab44-186@Mathy.com</a> 608-799-5337</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Trailer Lab #44-189</p> <p>Derek Fredrixon <a href="mailto:Lab44-189@Mathy.com">Lab44-189@Mathy.com</a> 608-799-5716</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Trailer Lab #44-188</p> <p>Derek Fredrixon <a href="mailto:Lab44-188@Mathy.com">Lab44-188@Mathy.com</a> 608-304-8747</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T164 Method A, T30, T166, T209, T269, T312, T331, ASTM D2950.</p>	<p>December 17, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>MCI Lab 1 N6504 Hwy 73 Princeton, WI 54968</p> <p>Trailer Lab</p> <p>Paul Buchen <a href="mailto:Paul.buchen@mashuda.com">Paul.buchen@mashuda.com</a> 920-229-3165</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Soils: T89, T89, T90, ASTM D1140.</p>	<p>December 10, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Michels Materials - Brownsville Lab 817 West Main Street Brownsville, WI 53006</p> <p>Lab #1</p> <p>Eric Zeinert <a href="mailto:ezeinert@michels.us">ezeinert@michels.us</a> 920-583-3132</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability (WisDOT Test Method), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, AMRL's Proficiency Sample Program.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T198, T309, R39, R60.</p> <p>Soils: T89, T90, T99, T180, T265, T310.</p>	<p>December 16, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Michels Materials – Neenah Lab 700 Tullar Road Neenah, WI 54956</p> <p>Lab #2</p> <p>Eric Zeinert <a href="mailto:ezeinert@michels.us">ezeinert@michels.us</a> 920-727-1688</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability (WisDOT Test Method), T11, T27, T255, ASTM D4791, R76, R90.</p>	<p>December 16, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Michels Materials Waterloo Lab W11184 Hubbleton Road Waterloo, WI 53594</p> <p>Eric Zeinert <a href="mailto:ezeinert@michels.us">ezeinert@michels.us</a> 920-478-2084</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability (WisDOT Test Method), T11, T27, T255, ASTM D4791, R76, R90.</p>	<p>December 16, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Michels Materials Trailer Laboratories 817 West Main St. Brownsville, WI 53006</p> <p>Trailer Lab #: D1015.</p> <p>Eric Zeinert <a href="mailto:ezeinert@michels.us">ezeinert@michels.us</a> 920-583-3132</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability -WisDOT Test Method, T11, T27, T255, ASTM D4791, R76, R90.</p>	<p>December 16, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Michels Materials Trailer Laboratories 817 West Main St. Brownsville, WI 53006</p> <p>Trailer Lab #: D1021.</p> <p>Eric Zeinert <a href="mailto:ezeinert@michels.us">ezeinert@michels.us</a> 920-583-3132</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability -WisDOT Test Method, T11, T27, T255, ASTM D4791, R76, R90.</p>	<p>December 16, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Michels Materials Franksville Lab 2916 N. Sylvania Ave. Franksville, WI 53126</p> <p>Eric Zeinert <a href="mailto:ezeinert@michels.us">ezeinert@michels.us</a> 920-583-3132</p>	<p>Concrete Mix: T22, T23, T97, R39.</p>	<p>December 16, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Michels Materials - Janesville Lab 4712 North John Paul Rd. Janesville, WI 53563</p> <p>Eric Zeinert <a href="mailto:ezeinert@michels.us">ezeinert@michels.us</a> 920-583-3132</p>	<p>Concrete Mix: T22, T23, T97, R39.</p>	<p>December 16, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Modern Ready Mix (Kohner Materials) 4980 West 6<sup>th</sup> Street Goodview, MN 55987</p> <p>Michael Kohner <a href="mailto:mkohner@kohnermaterials.com">mkohner@kohnermaterials.com</a> 507-454-5093</p>	<p>Aggregate: T11, T27, T255, R76.</p> <p>Concrete Mix: T22, T23, T119, T152-Air Content, T152-Air Meter Calibration, T309, R39, R60.</p>	<p>December 7, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Murphy's Construction Company 4905 W Prospect Ave Appleton, WI 54912</p> <p>Erin Ferg <a href="mailto:Erin.ferg@murphyinc.org">Erin.ferg@murphyinc.org</a> 920-750-9583</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Asphalt Mix Design (CMM 8-66.2), Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T305, T312, T331, ASTM D2950.</p> <p>Concrete Mix: T22, T23, T24, T119, T152, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310.</p>	<p>December 28, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Murphy's Construction Company 4905 W Prospect Ave Appleton, WI 54912</p> <p>Trailer Lab #2955</p> <p>Erin Ferg <a href="mailto:erin.ferg@murphyinc.org">erin.ferg@murphyinc.org</a> 920-750-9583</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T255, ASTM D4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Asphalt Mix Design (CMM 8-66.2), Extractions (T308 WisDOT Modified), Extractions (T164 Method A), Extractions (T164 Method B), Extractions (ASTM D8159 WisDOT Modified), T30, T166, T209, T269, T305, T312, ASTM D2950.</p> <p>Soils: T88, T99, T180, T310.</p>	<p>January 13, 2021</p>	<p>January 13, 2021</p>	<p>December 31, 2021</p>

<p>Northeast Asphalt, Inc. Larsen 4515 Cty. Rd. II Larsen, WI 54947</p> <p>Lab #: 354163</p> <p>Karl Runstrom <a href="mailto:krunstrom@neasghalt.com">krunstrom@neasghalt.com</a> 920-757-7585</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T84, T85, T255, ASTM D 4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331.</p>	<p>December 15, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Northeast Asphalt, Inc. De Pere 5118 Video Lane De Pere, WI 54115</p> <p>Lab #: 354067</p> <p>Karl Runstrom <a href="mailto:krunstrom@neasghalt.com">krunstrom@neasghalt.com</a> 920-757-7585</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331.</p>	<p>December 15, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Northeast Asphalt, Inc. Shawano W5660 Castle Road Shawano, WI 54166</p> <p>Lab #: 354065</p> <p>Karl Runstrom <a href="mailto:krunstrom@neasghalt.com">krunstrom@neasghalt.com</a> 920-757-7585</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T84, T255, ASTM D 4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312.</p>	<p>December 15, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Northeast Asphalt, Inc. Green Bay Lab 1524 Atkinson Drive Green Bay, WI 54303</p> <p>Lab #: 354181</p> <p>Karl Runstrom <a href="mailto:krunstrom@neasghalt.com">krunstrom@neasghalt.com</a> 920-757-7585</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T305, T312, T331.</p>	<p>December 15, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Northeast Asphalt, Inc. Menasha Lab 2500 Coldspring Road Appleton, WI 54914</p> <p>Karl Runstrom <a href="mailto:krunstrom@neasghalt.com">krunstrom@neasghalt.com</a> 920-757-7585</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T305, T312.</p>	<p>December 16, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Northeast Asphalt, Inc., Eden Lab W3194 County Road F Eden, WI 53019</p> <p>Karl Runstrom <a href="mailto:krunstrom@neasghalt.com">krunstrom@neasghalt.com</a> 920-757-7585</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T305, T312.</p>	<p>December 16, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Northeast Asphalt, Inc. W6380 Design Drive Greenville, WI 54942</p> <p>Trailer: 354144, 345145</p> <p>Karl Runstrom <a href="mailto:krunstrom@neasghalt.com">krunstrom@neasghalt.com</a> 920-757-7585</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T84, T85, T255, ASTM D 4791, R76, R90.</p>	<p>December 15, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Northeast Asphalt, Inc. W6380 Design Drive Greenville, WI 54942</p> <p>Portable Trailer: 354059.</p> <p>Karl Runstrom <a href="mailto:krunstrom@neasghalt.com">krunstrom@neasghalt.com</a> 920-757-7585</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p>	<p>December 15, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Northeast Asphalt, Inc. W6380 Design Drive Greenville, WI 54942</p> <p>Trailer Labs: 05411, 05521, 154034, 154307, 354073, 354104, 354201, 354186, 354202.</p> <p>Karl Runstrom <a href="mailto:krunstrom@neasphalt.com">krunstrom@neasphalt.com</a> 920-757-7585</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T305, T312, T331.</p>	<p>December 15, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Northeast Asphalt, Inc. W6380 Design Drive Greenville, WI 54942</p> <p>Trailer Lab #s: 05412, 05413.</p> <p>Karl Runstrom <a href="mailto:krunstrom@neasphalt.com">krunstrom@neasphalt.com</a> 920-757-7585</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T305, T312, T331.</p>	<p>December 15, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Northeast Asphalt, Inc. W6380 Design Drive Greenville, WI 54942</p> <p>Trailer Lab #s: 154307, 15410.</p> <p>Karl Runstrom <a href="mailto:krunstrom@neasphalt.com">krunstrom@neasphalt.com</a> 920-757-7585</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312.</p>	<p>December 15, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Northeast Asphalt, Inc. Green Bay Lab W. 6380 Design Dr. Greenville, WI 54942</p> <p>Trailer Lab #354220</p> <p>Karl Runstrom <a href="mailto:krunstrom@neasphalt.com">krunstrom@neasphalt.com</a> 920-757-7585</p>	<p>Aggregate: Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T305, T312, T331.</p>	<p>December 15, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>



<p>Northeast Asphalt, Inc. - Greenville MTC * W6380 Design Drive Greenville, WI 54942</p> <p>Randy Kennedy <a href="mailto:rkennedy@walbecgroup.com">rkennedy@walbecgroup.com</a> 906-757-7582</p>	<p>Aggregate: WisDOT Fracture (Coarse agg.), Permeability (WisDOT Test Method), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, T96, T103, T104, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, T30, T166, T209, T269, T312, Asphalt Design Method (CMM 8-66.2), Extractions (ASTM D8159 WisDOT Modified), T305, T331.</p> <p>Soils: T89, T90.</p>	<p>March 8, 2021</p>	<p>March 8, 2021</p>	<p>December 31, 2021</p>
<p>Northern Lakes Concrete Inc. 8075 County Hwy D Eagle River, WI 54521</p> <p>Mark Olejniczak <a href="mailto:molejniczak@pitlikandwick.com">molejniczak@pitlikandwick.com</a> 715-477-3367</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T84, T85, T90, T255, ASTM D4791, R76, R90.</p> <p>Concrete Mix: T22, T23, T119, T152, T309, R39, R60.</p> <p>Soils: T88, T99, T100, T180, T310.</p>	<p>December 8, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Nummelin Testing Services, Inc. 5620 Woodland Drive Waunakee, WI 53597</p> <p>Bruce Nummelin <a href="mailto:bnummelin@nummelintesting.com">bnummelin@nummelintesting.com</a> 608-849-9120</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T89, T90, T255, R76, R90.</p> <p>Asphalt Mix: ASTM D2950.</p> <p>Concrete Mix: T22, T23, T119, T152-Air Content, T152-Air Meter Calibration, T231, T309.</p> <p>Soils: T88, T89, T90, T99, T180, T265, T310, ASTM D 422, ASTM D 1140, R58.</p>	<p>December 7, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Nummelin Testing Services, Inc. 3217 Whiting Avenue Stevens Point, WI 54481</p> <p>Bruce Nummelin <a href="mailto:bnummelin@nummelintesting.com">bnummelin@nummelintesting.com</a> 715-341-7974</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T89, T90, T255, R76, R90.</p> <p>Asphalt Mix: ASTM D2950.</p> <p>Concrete Mix: T22, T23, T119, T152-Air Content, T152-Air Meter Calibration, T231, T309.</p> <p>Soils: T88, T89, T90, T99, T180, T265, T310, ASTM D 1140, R58.</p>	December 7, 2020	January 1, 2021	December 31, 2021
<p>Payne &amp; Dolan, Inc. W259 N8150 Hwy 164 Sussex, WI 53089</p> <p>Field Lab #: 154180</p> <p>Kathleen Peratt <a href="mailto:kperatt@walbecgroup.com">kperatt@walbecgroup.com</a> 262-524-1800</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312.</p>	December 8, 2020	January 1, 2021	December 31, 2021
<p>Payne &amp; Dolan, Inc. 6145 Cottonwood Trail Fitchburg, WI 53719</p> <p>Field Lab#: 154138 C-5</p> <p>Kathleen Peratt <a href="mailto:kperatt@walbecgroup.com">kperatt@walbecgroup.com</a> 262-524-1800</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T312.</p>	December 8, 2020	January 1, 2021	December 31, 2021
<p>Payne &amp; Dolan, Inc. 5416 Easy Street Waunakee, WI 53597</p> <p>Field Lab#: 154139 C-6</p> <p>Kathleen Peratt <a href="mailto:kperatt@walbecgroup.com">kperatt@walbecgroup.com</a> 262-524-1800</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T312.</p>	December 8, 2020	January 1, 2021	December 31, 2021

<p>Payne &amp; Dolan, Inc. 171 CTH MM Brooklyn, WI 53521</p> <p>Trailer Lab#: 15332</p> <p>Kathleen Peratt <a href="mailto:kperatt@walbecgroup.com">kperatt@walbecgroup.com</a> 262-524-1800</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T255, ASTM D4791, R76, R90.</p>	<p>December 8, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Payne &amp; Dolan, Inc. 6211 Rawson Ave Franklin WI 53132</p> <p>Field Lab #: 154140</p> <p>Kathleen Peratt <a href="mailto:kperatt@walbecgroup.com">kperatt@walbecgroup.com</a> 262-524-1800</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T312.</p>	<p>December 8, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Payne &amp; Dolan, Inc. 3211 Rawson Ave Franklin WI 53132</p> <p>Aggregate Field Lab #: 154255</p> <p>Kathleen Peratt <a href="mailto:kperatt@walbecgroup.com">kperatt@walbecgroup.com</a> 262-524-1800</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T85, T255, R76, R90.</p>	<p>December 8, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Payne &amp; Dolan, Inc. W6615 Hwy 12 Whitewater, WI 53190</p> <p>Trailer Lab #:154287</p> <p>Kathleen Peratt <a href="mailto:kperatt@walbecgroup.com">kperatt@walbecgroup.com</a> 262-524-1800</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, T30, T166, T209, T269, T312, Extractions (T308 WisDOT Modified).</p>	<p>March 10, 2021</p>	<p>March10, 2021</p>	<p>December 31, 2021</p>

<p>Payne &amp; Dolan, Inc. 5507 W. Rawson Ave Franklin WI 53132</p> <p>Trailer Lab #:154288</p> <p>Kathleen Peratt <a href="mailto:kperatt@walbecgroup.com">kperatt@walbecgroup.com</a> 262-524-1800</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312.</p>	<p>December 8, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Payne &amp; Dolan, Inc. W217 S8415 Crowbar Road Muskego, WI 53150</p> <p>Field Lab #: 154141</p> <p>Kathleen Peratt <a href="mailto:kperatt@walbecgroup.com">kperatt@walbecgroup.com</a> 262-524-1800</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312.</p>	<p>December 8, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Payne &amp; Dolan, Inc. W217 S8415 Crowbar Road Muskego, WI 53150</p> <p>Trailer Lab #: 15377</p> <p>Kathleen Peratt <a href="mailto:kperatt@walbecgroup.com">kperatt@walbecgroup.com</a> 262-524-1800</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T255, ASTM D4791, R76, R90.</p>	<p>December 8, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Payne &amp; Dolan, Inc. 2020 Oakes Road Racine, WI 53406</p> <p>Field Lab #: 154142</p> <p>Kathleen Peratt <a href="mailto:kperatt@walbecgroup.com">kperatt@walbecgroup.com</a> 262-524-1800</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312.</p>	<p>December 8, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Payne &amp; Dolan, Inc. 1740 120<sup>th</sup> Ave. Kenosha, WI 53144</p> <p>Field Lab #: 154277</p> <p>Kathleen Peratt <a href="mailto:kperatt@walbecgroup.com">kperatt@walbecgroup.com</a> 262-524-1800</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312.</p>	<p>December 8, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Payne &amp; Dolan, Inc. 2604 WI 120 Lake Geneva WI 53147</p> <p>Field Lab #: 154352</p> <p>Kathleen Peratt <a href="mailto:kperatt@walbecgroup.com">kperatt@walbecgroup.com</a> 262-524-1800</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312.</p>	<p>December 8, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Payne &amp; Dolan, Inc. W6615 Highway 12 Whitewater, WI 53190</p> <p>Trailer Lab #154284</p> <p>Kathleen Peratt <a href="mailto:kperatt@walbecgroup.com">kperatt@walbecgroup.com</a> 262-524-1800</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T166, T209, T269, T312.</p>	<p>December 8, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Payne &amp; Dolan, Inc. 5189 Aurora Rd. Hartford, WI 53027</p> <p>Trailer Lab #154305 C-8</p> <p>Kathleen Peratt <a href="mailto:kperatt@walbecgroup.com">kperatt@walbecgroup.com</a> 262-524-1800</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312.</p>	<p>December 8, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Payne &amp; Dolan, Inc. 28327 W. Route 173 Antioch, IL 60002</p> <p>Field Lab #154143</p> <p>Kathleen Peratt <a href="mailto:kperatt@walbecgroup.com">kperatt@walbecgroup.com</a> 262-524-1800</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312.</p>	<p>December 8, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Payne &amp; Dolan, Inc. 677 Peasant Valley Rd. West Bend, WI 53090</p> <p>Trailer Lab#: 154350</p> <p>Kathleen Peratt <a href="mailto:kperatt@walbecgroup.com">kperatt@walbecgroup.com</a> 262-524-1800</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312.</p>	<p>December 8, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Payne &amp; Dolan, Inc. 2759 Scenic Rd. Richfield, WI 53076</p> <p>Trailer Lab #: 154351</p> <p>Kathleen Peratt <a href="mailto:kperatt@walbecgroup.com">kperatt@walbecgroup.com</a> 262-524-1800</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312.</p>	<p>December 8, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Payne &amp; Dolan, Inc. N6W23034 Bluemound Road Waukesha, WI 53186</p> <p>Lab #: C-20</p> <p>Kathleen Peratt <a href="mailto:kperatt@walbecgroup.com">kperatt@walbecgroup.com</a> 262-524-1800</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T312, T331.</p>	<p>December 8, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Payne &amp; Dolan Gladstone Design Lab * 3560 Sjoquist Drive Gladstone, MI 49837</p> <p>Scott VanEnkevort <a href="mailto:svanenkevort@walbecgroup.com">svanenkevort@walbecgroup.com</a> 906-428-5119</p>	<p>Aggregate: WisDOT fracture (coarse), Permeability (WisDOT Test Method), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, T96, T103, T104.</p> <p>Asphalt Mix: CMM/QMP Sampling, T166, T209, T269, T312, Asphalt Mix Design (CMM 8-66.2), T30, Extractions (ASTM D8159 WisDOT Modified), T305, T331.</p>	<p>March 8, 2021</p>	<p>March 8, 2021</p>	<p>December 31, 2021</p>
<p>Payne &amp; Dolan, Inc. - Waukesha/Pewaukee MTC * W228 N683 Westmound Drive Waukesha, WI 53186</p> <p>Greg Mamerow <a href="mailto:gmamerow@walbecgroup.com">gmamerow@walbecgroup.com</a> 262-524-1731</p>	<p>Aggregate: WisDOT Fracture (Coarse agg.), Permeability (WisDOT Test Method), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, T96, T103, T104, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, T30, T166, T209, T269, T312, Asphalt Design Method (CMM 8-66.2), Extractions (ASTM D8159 WisDOT Modified); T305, T331.</p> <p>Soils: T89, T90.</p>	<p>March 8, 2021</p>	<p>March 8, 2021</p>	<p>December 31, 2021</p>
<p>Payne &amp; Dolan Binder Laboratory * 301 E Washington Street Milwaukee, WI 76131</p> <p>Carlton Travis <a href="mailto:ctravis@walbecgroup.com">ctravis@walbecgroup.com</a> 262-366-5146</p>	<p>Asphalt Mix: T164 Method A.</p>	<p>April 23, 2021</p>	<p>April 23, 2021</p>	<p>December 31, 2021</p>

<p>Peters Concrete Company 1516 Atkinson Drive Green Bay, WI 54303</p> <p>Jared Peters <a href="mailto:PCClab121@tds.net">PCClab121@tds.net</a> 920-494-3700</p>	<p>Aggregate: WISDOT Fracture (Coarse), T11, T27, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Concrete: T22, T23, T119, T152-Air Content, T152-Air Meter Calibration, T309, R39, R60.</p> <p>Soils: T88, T89, T90, ASTM D1140.</p>	December 8, 2020	January 1, 2021	December 31, 2021
<p>Pitlik and Wick, Inc. 8075 County Hwy D Eagle River, WI 54521</p> <p>Mark Olejniczak <a href="mailto:molejniczak@pitlikandwick.com">molejniczak@pitlikandwick.com</a> 715-477-3367</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T84, T85, T90, T255, ASTM D 4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Asphalt Mix Design (CMM 8-66.2), Extractions (T308 WisDOT Modified), Extractions (T164 Method A), T30, T166, T209, T269, T305, T312, T331, ASTM D2950.</p> <p>Concrete: T152-Air Meter Calibration.</p> <p>Soils: T88, T99, T100, T180, T310.</p>	December 8, 2020	January 1, 2021	December 31, 2021
<p>Pitlik and Wick, Inc. 8075 County Hwy D Eagle River, WI 54521</p> <p>Trailer Lab</p> <p>Mark Olejniczak <a href="mailto:molejniczak@pitlikandwick.com">molejniczak@pitlikandwick.com</a> 715-477-3367</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Extractions (T308 WisDOT Modified), Extractions (T164 Method A), T30, T166, T209, T269, T312, ASTM D2950.</p>	December 8, 2020	January 1, 2021	December 31, 2021
<p>P O B Materials 5009 Coye Drive Steven Point, WI 54481</p> <p>Lab Number POB01</p> <p>Dan St. Pierre <a href="mailto:dans@pobinc.com">dans@pobinc.com</a> 715-498-0764</p>	<p>Aggregate: WisDOT fracture (coarse), T11, T27, T89, T90, T255, ASTM D 4791, R76, R90.</p> <p>Concrete: T22, T23, T97, T119, T152, T198, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T180, T265, T310, ASTM D422, ASTM D1140.</p>	December 3, 2020	January 1, 2021	December 31, 2021



<p>Premier Concrete Solutions 508 Cedar St. Pioneer, OH 43554</p> <p>James Sobek <a href="mailto:James.sobek@premiereadmix.com">James.sobek@premiereadmix.com</a> 800-503-3418</p>	<p>Aggregate: WisDOT fracture (Coarse), Permeability (WisDOT Test Method), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, T96, T103, T104, AMRL's Proficiency Sample Program.</p> <p>Concrete: T22, T23, T24, T97, T119, T152, T198, T231, T277, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T100, T265, ASTM D1140.</p>	December 15, 2020	January 1, 2021	December 31, 2021
<p>Professional Services Industries, Inc. 12839 30<sup>th</sup> Avenue Chippewa Falls, WI 54729</p> <p>Logan Farb <a href="mailto:Logan.farb@intertek.com">Logan.farb@intertek.com</a> 715-738-2770</p>	<p>Aggregate: WisDOT fracture (Coarse), T11, T27, T255, ASTM D4791.</p> <p>Soils: T88, T99, T180, T310, ASTM D-422, ASTM D-1140.</p>	January 4, 2021	January 4, 2021	December 31, 2021
<p>Professional Services Industries, Inc. * 821 Corporate Court Waukesha, WI 53189</p> <p>Nicole Carlson <a href="mailto:Nicole.carlson@psiusa.com">Nicole.carlson@psiusa.com</a> 262-521-2125</p>	<p>Aggregate: WisDOT fracture (Coarse), Permeability (WisDOT Test Method), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, T30, Extractions (T308 WisDOT Modified), T166, T209, T269, T331, ASTM D2950.</p> <p>Concrete: T22, T23, T24, T97, T119, T152, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D 422, ASTM D 1140, R58.</p>	July 19, 2021	July 19, 2021	December 31, 2021

<p>QC Tech 315 76<sup>th</sup> St. Franksville, WI 53126</p> <p>Scott Wall <a href="mailto:gcscottwall@gmail.com">gcscottwall@gmail.com</a> 414-406-5839</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability (WisDOT Test Method), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T198, T231, T277, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, ASTM D 422, ASTM D 1140, R58.</p>	<p>December 11, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>QUEST Lab 1 2822 W Grand Ave. Wisconsin Rapids, WI 54495</p> <p>Tony Rosling <a href="mailto:Tony.rosling@questllc.biz">Tony.rosling@questllc.biz</a> 715-572-2750</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T89, T255, ASTM D4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, ASTM D2950.</p> <p>Concrete Mix: T22, T23, T97, T119, T152, T309, R39, R60.</p> <p>Soils: T89, T90, T180, T310.</p>	<p>December 7, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>R.G. Huston Company, Inc. 2561 Coffeytown Road Cottage Grove, WI 53527</p> <p>Dennis Richardson <a href="mailto:dennis@rghuston.com">dennis@rghuston.com</a> 608-255-9223</p>	<p>Aggregate: T11, T27, R76, R90.</p> <p>Concrete Mix: T23, T119, T152-Air Content, T309, R60.</p>	<p>December 22, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Rock Road Companies – Beloit Lab 301 W BR Townline Rd Beloit, WI 53511</p> <p>Steve Bloedow <a href="mailto:sbloedow@rockroads.com">sbloedow@rockroads.com</a> 608-289-7365</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability – WisDOT Test Method, T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T85, T84, T96, T103, T104.</p> <p>Asphalt Mix: CMM/QMP Sampling, CMM 8-66.2, Extractions (T308 WisDOT Modified), T30, Extractions (T164 Method A), Extractions (T164 Method B), T166, T209, T269, T305, T312, T331, ASTM D2950, ASTM 8159 WisDOT Modified).</p> <p>Soils: T89, T90, T99, T100, T180, T310, R58.</p>	December 10, 2020	January 1, 2021	December 31, 2021
<p>Rock Road Companies W6512 County Highway Y Monroe, WI 53566</p> <p>Trailer Lab</p> <p>Steve Bloedow <a href="mailto:sbloedow@rockroads.com">sbloedow@rockroads.com</a> 608-289-7365</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, T30, T166, T209, T269, T312, Extractions (T308 WisDOT Modified).</p>	December 10, 2020	March 18, 2021	December 31, 2021
<p>Rock Road Companies Materials Lab#1 W8682 Breezy Point Rd. Beaver Dam, WI 53916</p> <p>Trailer Lab</p> <p>Steve Bloedow <a href="mailto:sbloedow@rockroads.com">sbloedow@rockroads.com</a> 608-289-7365</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, T30, T166, T209, T269, T312, Extractions (T308 WisDOT Modified), T331.</p>	April 22, 2021	April 22, 2021	December 31, 2021

<p>Sheboygan County Transportation Dept. W5741 CTH J Plymouth, WI 53073</p> <p>Amy Wieland <a href="mailto:amy.wieland@sheboygancounty.com">amy.wieland@sheboygancounty.com</a> 920-459-3822</p>	<p>Aggregate: WisDOT Fracture (Coarse agg.), T11, T27, T255, ASTM D4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling.</p>	<p>December 15, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>SJK ENGINEERING 327 N 3<sup>rd</sup> St. Muscodia, WI 53573</p> <p>Keith Werthwein <a href="mailto:KEITHW@SJKENG.COM">KEITHW@SJKENG.COM</a> 608-574-6201</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T255, ASTM D4791, R76, R90.</p> <p>Concrete Mix: T22, T23, T119, T152, T309, R39, R60.</p>	<p>March 26, 2021</p>	<p>March 26, 2021</p>	<p>December 31, 2021</p>
<p>Soils &amp; Engineering Services, Inc. * 1102 Stewart Street Madison, WI 53713-4648</p> <p>Duane E. Reichel, P.E. <a href="mailto:duane@soils.ws">duane@soils.ws</a> 608-274-7600</p>	<p>Aggregate: WisDOT Fracture (Coarse agg.), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, T96, T103, T104, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: Extractions (T308 WisDOT Modified), Extractions (T164 Method A), Extractions (ASTM D8159 WisDOT Modified), T30, T166, T269, T331, ASTM D2950.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T198, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D 422, ASTM D 1140, R58.</p>	<p>December 15, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Sommers Construction Co., Inc. W7841 Smith St. Shiocton, WI 54170</p> <p>Michelle Mckewin <a href="mailto:mmckewin@sommersconst.com">mmckewin@sommersconst.com</a> 920-986-3301</p>	<p>Concrete Mix: T22, T23, T119, T152-Air Content, T152-Air Meter Calibration, T309, R60.</p>	<p>December 7, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Stark Pavement Corporation Hampton Lab 11710 W Hampton Ave Milwaukee, WI 53225</p> <p>Carl Johnson <a href="mailto:carlj@starkcorp.us">carlj@starkcorp.us</a> 414-466-7820</p>	<p>Aggregate: WisDOT Fracture (Coarse agg.), T11, T27, T84, T85, T255, ASTM D4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, T30, T166, T209, T269, T312, Asphalt Design Method (CMM 8-66.2), T308, Extractions (ASTM D8159 WisDOT Modified), T305, T331.</p> <p>Soils: T90.</p>	<p>April 21, 2021</p>	<p>April 21, 2021</p>	<p>December 31, 2021</p>
<p>Stark Pavement Corporation Portable Lab 1821 SE Frontage Rd Mount Pleasant, WI 53177</p> <p>Trailer Lab #1</p> <p>Carl Johnson <a href="mailto:carlj@starkcorp.us">carlj@starkcorp.us</a> 414-466-7820</p>	<p>Aggregate: WisDOT Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, T30, T166, T209, T269, T312, T308, T305, T331, ASTM D2950.</p> <p>Soils: T90.</p>	<p>April 21, 2021</p>	<p>April 21, 2021</p>	<p>December 31, 2021</p>
<p>Stark Pavement Corporation Portable Lab N51W23995 Lisbon Rd. Sussex, WI 53089</p> <p>Trailer Lab #2</p> <p>Carl Johnson <a href="mailto:carlj@starkcorp.us">carlj@starkcorp.us</a> 414-466-7820</p>	<p>Aggregate: WisDOT Fracture (Coarse agg.), T11, T27, T255, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, T30, T166, T209, T269, T312, T308, T331, ASTM D2950.</p> <p>Soils: T90.</p>	<p>April 21, 2021</p>	<p>April 21, 2021</p>	<p>December 31, 2021</p>

<p>Team Engineering, Inc. 118 E. Main Street Reedsburg, WI 53959</p> <p>Steve Alt <a href="mailto:salt@teamenginc.com">salt@teamenginc.com</a> 608-768-5075</p>	<p>Aggregate: R90.</p> <p>Concrete Mix: T23, T119, T152-Air Content, T152-Air Meter Calibration, T309, R60.</p>	<p>December 7, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Terracon Consultants, Inc. 9600 South 60<sup>th</sup> Street Franklin, WI 53132</p> <p>Andy Wendt <a href="mailto:Andy.wendt@terracon.com">Andy.wendt@terracon.com</a> 414-423-0255</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T255, R76, R90.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T180, T265, T310, ASTM D 422, ASTM D 1140, R58.</p>	<p>January 18, 2021</p>	<p>January 18, 2021</p>	<p>December 31, 2021</p>
<p>Toki &amp; Associates, Inc. 7100 W. Fond Du Lac Avenue Milwaukee, WI 53218</p> <p>Olaitan Olapo <a href="mailto:toki@tokiandassociates.com">toki@tokiandassociates.com</a> 414-463-2700</p>	<p>Aggregate: WisDOT Fracture (Coarse agg.), Permeability – WisDOT Test Method, T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Concrete Mix: T22, T23, T24, T119, T152-Air Content, T152-Aggregate Correction, T231, T309, R39, R60.</p>	<p>December 8, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Tri County Paving, Inc. N1423 County Rd I Arlington, WI 53532</p> <p>Ryan Jennaro <a href="mailto:rjennarotcp@gmail.com">rjennarotcp@gmail.com</a> 414-839-4720</p>	<p>Aggregate: WisDOT Fracture (Coarse Agg.), T11, T27, T84, T85, T255, ASTM D4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Asphalt Mix Design (CMM 8-66.2), Extractions (T308 WisDOT Modified), Extractions (T164 Method A), Extractions (T164 Method B), Extractions (ASTM D8159 WisDOT Modified), T30, T166, T209, T269, T305, T312, T331, ASTM D2950.</p>	<p>January 4, 2021</p>	<p>January 4, 2021</p>	<p>December 31, 2021</p>

<p>Trierweiler Construction &amp; Supply, Inc. 2916 S Cherry St. Marshfield, WI 54449</p> <p>Chris Lamb <a href="mailto:chris@tpaving.com">chris@tpaving.com</a> 715-421-9451</p>	<p>Aggregate: T11, T27, T255, ASTM D4791, R76, R90.</p> <p>Concrete Mix: T22, T23, T97, T119, T152, T198, T309, R39, R60.</p>	<p>December 10, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Trierweiler Construction &amp; Supply, Inc. 2916 S Cherry St. Marshfield, WI 54449</p> <p>Trailer Lab #1</p> <p>Chris Lamb <a href="mailto:chris@tpaving.com">chris@tpaving.com</a> 715-421-9451</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Concrete Mix: T22, T23, T97, T119, T152, T198, T309, R39, R60.</p>	<p>December 10, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Trierweiler Construction &amp; Supply, Inc. 2916 S Cherry St. Marshfield, WI 54449</p> <p>Trailer Lab #2.</p> <p>Chris Lamb <a href="mailto:chris@tpaving.com">chris@tpaving.com</a> 715-421-9451</p>	<p>Aggregate: T11, T27, T255, R76, R90.</p> <p>Concrete Mix: T22, T23, T97, T119, T152, T198, T309, R39, R60.</p>	<p>December 10, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Twin City Concrete Products Co. * 1370 Trout Brook Circle St. Paul, MN 55117</p> <p>Matthew Danielson <a href="mailto:mdanielson@cemstone.com">mdanielson@cemstone.com</a> 651-286-1274</p>	<p>Aggregate: T11, T27, T84, T85, T255, ASTM D4791, R76, R90.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T198, T231, T277, T309, R39, R60.</p>	<p>December 18, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Twin City Materials, Inc. 12154 40<sup>th</sup> Ave. Chippewa Falls, WI 54729</p> <p>Roseann Bowe <a href="mailto:lab@sennblacktop.com">lab@sennblacktop.com</a> 715-723-8527</p>	<p>Aggregate: WisDOT Fracture (Coarse Agg.), Permeability (WisDOT Test Method), T11, T27, T84, T85, T255, ASTM D4791, R76, R90.</p> <p>Asphalt Mix: CMM/QMP Sampling, Asphalt Mix Design (CMM 8-66.2), Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T305, T312, ASTM D2950.</p>	<p>May 5, 2021</p>	<p>May 5, 2021</p>	<p>December 31, 2021</p>
<p>Twin Port Testing II * 1301 N 3<sup>rd</sup> Street Superior, WI 54880</p> <p>Joe Berger <a href="mailto:jberger@twinporttesting.com">jberger@twinporttesting.com</a> 218-391-9463</p>	<p>Aggregate: T11, T27, T84, T85, T89, T255, ASTM D4791, R76, R90.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T231, T309, R39.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D422, ASTM D 1140, R58.</p>	<p>December 18, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Vinton Materials Testing 2705 N. Rapids Rd. Manitowoc, WI 54221</p> <p>Thomas Sand <a href="mailto:tsand@vintonwis.com">tsand@vintonwis.com</a> 920-973-8942</p>	<p>Aggregate: WisDOT fracture (coarse Agg.), T11, T27, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Concrete Mix: T22, T23, T97, T119, T152, T198, T231, T309, R39, R60.</p>	<p>December 11, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>
<p>Wabasha Ready Mix 905 Church Ave Wabasha, MN 55981</p> <p>Mike Kohner <a href="mailto:mkohner@kohnermaterials.com">mkohner@kohnermaterials.com</a> 651-565-3610</p>	<p>Aggregate: T11, T27, T255, R76.</p> <p>Concrete Mix: T23, T119, T152-Air Content, T309, R60.</p>	<p>December 7, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>



<p>Waukesha Design Lab * W228 N683 Westmound Drive Waukesha, WI 54318</p> <p>Stacy Glidden sglidden@walbecgroup.com 920-716-5822</p>	<p>Aggregate: WisDOT Fracture (Coarse agg.), Permeability (WisDOT Test Method), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, T96, T103, T104, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, T30, T166, T209, T269, T312, Asphalt Design Method (CMM 8-66.2), Extractions (ASTM D8159 WisDOT Modified), T305, T331.</p> <p>Soils: T90.</p>	<p>March 8, 2021</p>	<p>March 8, 2021</p>	<p>December 31, 2021</p>
<p>Westwood Professional Services. * One System Drive Appleton, WI 54914</p> <p>Paul R. Eggen, PG, CET <a href="mailto:paul.eggen@omni.com">paul.eggen@omni.com</a> 920-830-6151</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability (WisDOT Test Method), T11, T27, T84, T85, T89, T90, T255, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T84, T85, T96, T104.</p> <p>Asphalt Mix: CMM/QMP Sampling, Asphalt Mix Design (CMM 8-66.2), Extractions (T308 WisDOT Modified), T30, T166, T209, T269, T305, T312, T331, ASTM D2950.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T198, T231, T309, R39, R60.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, T310, ASTM D422, ASTM D 1140, R58.</p>	<p>December 14, 2020</p>	<p>January 1, 2021</p>	<p>December 31, 2021</p>

<p>Yahara Materials, Inc. 315 Moravian Valley Rd Suite #9 Waunakee, WI 53597</p> <p>Jack Peterson <a href="mailto:jack@yahara.com">jack@yahara.com</a> 608-445-9120</p>	<p>Aggregate: Fracture (Course Agg.), T11, T27, T85, T89, T90, ASTM D4791, R76, R90.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using R74 Method A for Prep of P-4, T90 Using R74 Method A for Prep of P-4, T85, T96, T103, T104, AMRL Proficiency Sample Program.</p>	<p>January 5, 2021</p>	<p>January 4, 2021</p>	<p>December 31, 2021</p>
---	---	------------------------	------------------------	--------------------------

\* Indicates laboratory is AASHTO accredited.