## Wisconsin Facilities Frequently Requiring Repair and Reconstruction due to Emergency Events (F4R)

This list was updated in July 2022 to remove F4R facilities found not to meet the criteria for F4R designation.\*

No new F4R facilities have been added since June 2020.\*\*

	County	Map Number†	F4R Road Segment	F4R Road Segment Endpoints	F4R Road Segment Length (Miles)	Event 1 Damage Year	Event 2 Damage Year	Event 1 Damage Endpoints	Event 2 Damage Endpoints	Event 1 Damage Detail	Event 2 Damage Detail	Event 1 WI Emrg. Declar. ID	Event 2 WI Emrg. Declar. ID
1	Ashland/ Bayfield	24	CTH E	USH 63 - STH 112	8.70	2017	2020	Four Corners Road Intersection	Molan Hill (WI-18072)	Unspecified	Unspecified	2016-207	2018-295
2	Bayfield	3	СТН Е	Mason Delta Rd - Faith Church Rd	7.26	2016	2018	CTH M - Old D Rd	CTH H - Andrew Anderson Rd; Andrew Anderson Rd Moonshine Alley Rd; Moonshine Alley Rd - Faith Church Rd	Roadway washout	Culvert, pavement, & shoulder damage; ditch washouts	2016-207	2018-295
3	Buffalo	7	STH 88	CTH E - Town of Lincoln	2.42	2016	2016	Multiple Locations <sup>1</sup>	WI 35 - WI 95	Structure damage, roadway & sideslope washout	Complete roadway & shoulder washout	2016-211	2016-215
4	Buffalo	8	СТН Е	CTH U - Bremer Ridge Rd	6.09	2016	2017	WI 35 - WI 95	CTH U - Bremer Ridge Road	Complete roadway & shoulder washout	Damaged bridge approaches & slope failures	2016-215	2017-249
5	Buffalo	9	СТН С	STH 95 - Jessie Trail Rd	7.81	2016	2017	WI 95 - CTH CC	Jessie Trail Road - STH 95	Roadway & slope washouts	Large slope & shoulder failure	2016-211	2017-249
6	Douglas	1	СТН А	Hammond Ave - Dopp Rd	0.50	2012	2018	Multiple Locations <sup>2</sup>	Tri Lakes Rd - CTH B	Road washout, culvert failed	Shoulder washouts	2012-74	2018-295
7	Douglas	2	Woodlawn Rd	58th St N - CTH A	0.78	2012	2018	Woodlawn Ave, C. of Superior	CTH A - N 58th St E	Shoulder & fore slope washed out	Complete roadway washout	2012-74	2018-295
8	Iron	6	СТН А	Harbor Dr -	0.49	2016	2018	Culvert and Marina Roadway in Town of Saxon	Oronto Creek Bridge B-26-0044	Structure & roadway washout	Flood repair	2016-202	2018-295
9	La Crosse	14	CTH VV	CTH T - North County Line	0.19	2017	2018	CTH T TO NCL (SITE WI-17-017)	0.5 MI NORTH OF CTH T (SITE WI-16- 120)	Culvert failure & shoulder washout	Unspecified	2017-249	2018-305
10	La Crosse	16	СТН FO	CTH F - CTH OA	1.91	2017	2018	CTH F - CTH OA	CTH F - CTH OA	Shoulder washouts	Ditch & shoulder damage	2017-249	2018-305
11	La Crosse	18	СТН Ј	CTH U - STH 16	1.27	2017	2018	CTH U - STH 16	CTH U - STH 16	Shoulder & pavement edge repair (water over road)	Slope, shoulder, & guardrail failures	2017-249	2018-305
12	Monroe	20	СТН Ј	CTH Y - STH 27	4.79	2017	2018	STH 27 - CTH Y	STH 27 - CTH Y	Culverts, shoulders washed out	Slope, shoulder & pavement repairs	2017-249	2018-305
13	Monroe	21	СТН ХХ	STH 27 - CTH U	6.40	2017	2018	STH 27 - CTH U (SITE WI-17-031)	STH 27 - CTH U	Scour around abutments & pier, shoulder washouts & embankment failures	Slope, shoulder, & pavement repairs	2017-249	2018-305
14	Trempealeau	10	СТН Т	STH 95 - Burlington Rd	3.58	2016	2017	STH 95 - Burlington Rd	USH 53 - STH 95	Damage to culvert pipe, pavement, shoulders, and slopes	Embankment washout, rip-rap washout around culverts	2016-215	2017-249
15	Trempealeau	11	СТН Т	CTH D - CTH D	2.92	2016	2017	WI 95 - Co Line	CTH N - CTH DD	Culvert failure and shoulder washout	Slope and rip-rap washout, culvert at D & N collapsed	2016-215	2017-249
16	Trempealeau	12	CTH D	CTH T - T North Bend	9.27	2016	2017	CTH T - T North Bend	CTH T - T North Bend	Culvert failure & shoulder washout	Slope and rip-rap washout, culvert at D & N collapsed	2016-215	2017-249
17	Trempealeau	13	CTH D	CTH N - CTH T	6.93	2016	2017	CTH N - CTH T	CTH N - CTH T	Culvert failure and shoulder washout	Slope and rip-rap washout, culvert at D & N collapsed	2016-215	2017-249
18	Vernon	19	STH 162	СТН О - СТН К	6.03	2007	2018	Coon Creek Bridge; Stoddard - Chaseburg	Coon Creek Bridge, North CTH K - South CTH K JCT	Bridge pier armor damage, retaining wall collapse	Slope, shoulder, & scour washouts along US 14 & behind beam guard	2007-209	2018-305
19	Vernon	22	СТН Р	STH 27 - CTH D	6.12	2017	2018	STH 27 - CTH D	STH 27 - CTH D	Ditch & shoulder repairs	Roadway washout, slides, pavement repairs	2017-249	2018-305

Vernon	23	CTH P	STH 131 -	3.17	2017	2018	STH 131 - Valley	STH 131 - STH 82	Ditch & shoulder	Slope failure,	2017-249	2018-305
			Skyline Dr						repairs	washouts,		
										shoulders &		
										pavement repairs		
Vernon	25	СТН В	STH 56 -	0.17	2016	2017	Bridge area	STH 56 - CTH V	Scour holes	Ditch & shoulder	2016-215	2017-249
Vernon	25	CITE	СТН Ү	0.17	2010	2017	blidge dred	Sin So cint	shoulders, &	repairs	2010 215	2011 213
									ditches			
	Vernon Vernon			Vernon 25 CTH B STH 56 -	Vernon     25     CTH B     STH 56 -     0.17	Vernon     25     CTH B     STH 56 -     0.17     2016	Vernon     25     CTH B     STH 56 -     0.17     2016     2017	Vernon     25     CTH B     STH 56 -     0.17     2016     2017     Bridge area	Vernon     25     CTH B     STH 56 -     0.17     2016     2017     Bridge area     STH 56 - CTH Y	Vernon 25 CTH B STH 56 - CTH Y 0.17 2016 2017 Bridge area STH 56 - CTH Y Scour holes, shoulders, &	Vernon25CTH BSTH 56 - CTH Y0.1720162017Bridge areaSTH 56 - CTH YScour holes, shoulders, & pavement repairs	Vernon25CTH BSTH 56 - CTH Y0.1720162017Bridge areaSTH 56 - CTH YScour holes, shoulders, &Ditch & shoulder repairs2016-215

\* As this list of sites is reviewed periodically it might be determined that a given facility does not meet the F4R qualifying conditions (e.g., the distance between the two damage locations is too large, or the damage was due to factors other than the sever weather event). Such facilities are removed from the list and corresponding map.

\*\* As severe weather events resulting in emergency declarations occur, catastrophic damage locations will be reviewed to determine if warrant F4R Facility designation (a second instance of catastrophic damage in the same location); if they do, they will be added to this list and corresponding map.

<sup>+</sup> Map numbers are for identification purposes; they are not counts and they are not sequential or continuous

<sup>1</sup> WI 121-WI 35, B-06-0040, B-06-0103, B-06-0165, C-06-0002, C-06-0044, C-06-5705

<sup>2</sup> CTH E, .33 MI N. of CTH Z; CTH C, .49 MI N. of Perham Road; CTH C, 125 ft W. of Mertes Road; CTH E, .267 MI W. of CTH C connection to USH 53; CTH E, .378 MI E./S. of CTH C connection to USH 53