

## **January 2022 HSIS Enhancements and Bug Fixes of Note**

A new version of HSIS was released on 1/19/2022. The following is a list of some of the bugs fixed in this release. This release has no major enhancements.

If you discover any bugs or have suggestions for enhancements, please email [ryan.bowers@dot.wi.gov](mailto:ryan.bowers@dot.wi.gov). If you do find a bug, please provide as much information as possible about what structure you were working on, what browser you used, if you were using a mobile device or not, items you were editing or clicking on prior to the bug occurring, etc. The more information you provide, the better chance we have at determining the cause and fixing it. Any screenshots or videos you can take are helpful.

### **Enhancements**

- 1) The routine inspection procedures are now visible for all inspection types. The routine inspection procedures can only be edited during a routine inspection.
- 2) Inspection procedures can be entered for all inspection types.
- 3) A note was added to General Inventory > File stating "additional files may be located at county/region offices." This does not mean there ARE additional files at these offices, but there might be.
- 4) Additional CAD file types can be uploaded with an inspection.

### **Bug Fixes**

The following bugs were fixed with this version. Additional bugs not listed below were also fixed.

- 1) The bug causing a nullpointer to appear when clicking on certain entries under Inspection > History has been fixed.
- 2) A bug causing users to click "save" prior to navigating away from a structure that has an open inspection, even though the user didn't change anything, has been fixed.
- 3) The inventory tab for noise walls loads correctly.
- 4) When uploading a new cover photo, the image should refresh now.