



Substandard Sight Distance (County O)

Closely Spaced Access Points

Substandard Vertical Alignment

Substandard Vertical Alignment

Closely Spaced Access Points

Closely Spaced Access Points

Closely Spaced Access Points

**LEGEND**

- ◆ Potential Crash Rate Concern
- Closely Spaced Access Points
- Geometry below Minimum Standards

WIS 47 Corridor Study - Existing Conditions: County JJ to County O

County JJ to WIS 54 (Outagamie County)  
Project ID: 6240-14-00