




# US 51 Stoughton Road Corridor Study, exhibit - Crash diagrams, Voges to Broadway



### Intersection Crash Summaries



### Crash Type

- Angle
- Rear End
- Side Swipe
- Head On
- Deer/Other Animal
- Fixed Object
- Miscellaneous

### Map Legend

- Crash Incident
- Limited Access
- Highways
- Secondary Roads
- Other
- Highway Ramp
- Road Centerlines
- Surface Water

### Data Sources

Orthophotography: NAIP, 2008  
 Crash Data: Wisconsin Department of Transportation, 2005 - 2008  
 Major Roads: ESRI, 2006  
 Local Roads: Dane County Land Information Office

### Accuracy Note

Crash data shown was provided by the Wisconsin Department of Transportation. The data shown was located on 1:100,000 base maps based on measurements from known reference points. National Map Accuracy Standards for 1:100,000 scale data specify a minimum horizontal accuracy of plus or minus 167 feet. Therefore, enlarging the data to the scale shown on this map introduces inaccuracies; therefore, crash locations shown on this map are only approximate, and should be used to evaluate relative crash density and intensity.

1 inch = 400 feet  
12/15/2011

**VEHICLE CRASH INVENTORY**

2005 through 2008  
U.S. Highway 51  
(Stoughton Road)  
Corridor Study

5126 W. Terrace Drive  
Suite 111  
Madison, Wisconsin 53718  
608 | 242-1500  
www.graef-usa.com