


DETAIL A



Normal Crossings: Spillthrough Abutments

Source: HDS No. 1, *Hydraulics of Bridge Waterways*, FHWA, 1973.