


## PRELIMINARY ALTERNATIVES

### Spot Improvement Concepts: WIS 35 & Clinton St Intersection


## WIS 35 & Clinton St. Intersection

The WIS 35 & Clinton St intersection has one of the higher number of crashes within the WIS 35 corridor. This intersection has some geometric features that contribute to safety concerns for vehicular traffic, bicyclists, and pedestrians.




## Bike / Pedestrian Safety

The sidewalk along the west side of WIS 35 ends short of the crosswalk. Pedestrians reaching the end of the sidewalk cannot activate the pedestrian signals. Opportunities to improve this situation will be explored.



View of WIS 35 Looking Southwest



WIS 35 & Clinton St Intersection Aerial

