Pedestrian and Bicycle Facilities

CROSSWALK LOCATIONS

EXISTING MARKED

Marked crosswalk at three








BICYCLE/PEDESTRIAN CRASHES:

From 2017-2021, there were three documented pedestrian or bicycle crashes within the study area:

- 1. Between US 151/East Washington Avenue and Anderson Street
- 2. Bicycle crossing the East Washington Avenue westbound right-turn lane to get to the porkchop island
- 3. North leg of the Anderson Street intersection





Rieder Rd



LEGEND

- **Existing Pedestrian Facilities**
- **Existing Bicycle Facilities**
- Existing Paved Shoulder
- - Proposed Shared Use Path*
- Shared Use Path Planned by Others
 - Proposed Bus Rapid Transit Route
 - Madison Metro Bus Stop
 - Bicycle Repair Station
 - **Bicycles Prohibited**



SHARE YOUR THOUGHTS

Bicycle and Pedestrian Accomodations





