

Study Needs: Roadway Geometrics

Roadway and geometric deficiencies can lead to safety and operational concerns. Two locations on the US 51 corridor with recorded crashes that appear to be associated with roadway geometrics are ① the intersection skew of the north leg of the intersection at US 51 and US 151/East Washington Avenue and ② the two horizontal curves north of Pierstorff Street.

