# **>>**

## **Pedestrian and Bicycle Facilities**

#### **CROSSWALK LOCATIONS**

EXISTING MARKED

Marked crosswalk at three



KINSMAN BLVD



ANDERSON S




US 151 / E. WASHINGTON AV

## BICYCLE/PEDESTRIAN CRASHES:

From 2017-2021, there were three documented pedestrian or bicycle crashes within the study area:

- Between US 151/East Washington Avenue and Anderson Street
- 2. Bicycle crossing the East Washington Avenue westbound right-turn lane to get to the porkchop island
- 3. North leg of the Anderson Street intersection







### LEGEND

- Existing Pedestrian Facilities
- Existing Bicycle Facilities
- Existing Paved Shoulder
- - Proposed Future Bike/Ped. Facilities\*
- --- Path Planned by Others
- --- Future Bus Rapid Transit Route
- Madison Metro Bus Stop
- Bicycle Repair Station
- Bioyete Repair Sta
- Bicycles Prohibited

ps://data-cityofmadison.opendata.arcgis.com/



### **SHARE YOUR THOUGHTS**

**Bicycle and Pedestrian Accomodations** 

place sticky note here





